

Configuration Guide to
VDSL2 and ADSL2/2+ NIM
ON
ISR4400 AND ISR4300 Routers

Table of Contents

Table of Contents.....	2
1. Introduction to VDSL2 and ADSL 2/2+ NIM.....	4
1.1. Variants of xDSL NIMs	5
1.2. DSL Feature Specifications	5
2. Configuring DSL	6
2.1. Configuring ADSL.....	6
2.2. Configuring VDSL.....	7
2.2.1. VDSL2 Single-wire (8a to 17a).....	7
2.2.2. VDSL2 30a profile	7
2.2.3. VDSL2 Bonding	7
2.3. DSL configuration restrictions.....	8
2.4. DSL configuration examples.....	8
3. Features supported in IOS-XE 3.14 over xDSL NIMs	9
3.1. Firmware upgrade and downgrade	9
3.2. Dynamic Bandwidth Change for ATM PVCs	21
3.3. ATM Oversubscription for DSL.....	26
3.4. Multilink PPP (MLPPP) bundling	28
3.4.1. Multilink PPP Minimum Links Mandatory.....	28
3.4.2. MLPPP bundling of interfaces	28
3.4.3. ATM Multilink PPP Support on Multiple VCs	28
3.5. ATM Routed Bridge Encapsulation (RBE)	29
3.6. RBE Client Side Encapsulation with QoS.....	29
3.7. ATM Cell Loss Priority (CLP) Bit Marking	29
3.8. ATM Cell Loss Priority (CLP) Setting	29
3.9. ATM OAM Loopback Mode Detection.....	29
3.10. PPPoEoA over ATM AAL5Mux.....	29
3.11. ATM Conditional Debug Support.....	30
3.12. PPP over ATM (IETF-Compliant).....	30
3.13. MQC Policy Map Support on Configured VC Range ATM	30

3.14.	Default Route on a PPP Virtual Access Interface	30
3.15.	Modular QoS CLI (MQC) Unconditional Packet Discard.....	30
3.16.	PPPoE spec conformance with PADT message.....	30
3.17.	PPPoE enhancement with RFC 4638.....	30
3.18.	IP to ATM CoS, per-VC WFQ and CBWFQ QoS: PPPoE QoS Markings	30
3.19.	QoS: PPPoE QoS Markings of .1P bits in S (AOL)	31
3.20.	IP-to-ATM CoS	31
3.21.	LLQ (Low Latency Queueing).....	31
3.22.	QoS on Dialer.....	31
3.23.	VC bundling.....	31
4.	Show and Debug commands.....	31
4.1	Module specific show commands.....	34
4.2	Useful CLIs for debugging issues related to packet flow specific to ATM PVC	44
4.3	DSL debug commands.....	47
4.4	Collecting training-log	47
5.	Sample configurations.....	50
5.1	Sample MLPPP configs and show commands.....	50
5.2.	Sample PPPoA configuration	54
5.3.	Sample PPPoEoA configuration	54
6	Known limitations/Restrictions.....	55
6.1	PVC under sub-interface only	55
6.2	Maximum of 8 PVCs supported on a physical interface	55
6.3	MLPPP bundle across DSL interfaces	56
6.4	ATM Virtual Circuit Bundles license requirement.....	58
6.5	ATM Multilink PPP Support on Multiple VCs and MLPPP bundling of interfaces.....	58

1. Introduction to VDSL2 and ADSL 2/2+ NIM

The Cisco multimode VDSL2 and ADSL1/2/2+ NIM provides 1-port (2-pair) multimode VDSL2 and ADSI2+ WAN connectivity. In combination with ISR4400 and ISR4300 Routers, this NIM provides high-speed digital data transmission between customer premises equipment (CPE) and the central office (DSL access multiplexer [DSLAM]), usually located on the telephone company premises. This capability enables service providers and resellers to offer additional services such as business-class security; voice, video, and data; differentiated classes of service (QoS). These NIMs can be plugged in to NIM slots and in SM slots using SM-X-NIM-ADPTR carrier cards.

Software Support:

All variants of xDSL NIMs (refer sec 1.1) supported on CISCO IOS-XE Software Release XE3.14 onwards.

Embedded Firmware:

39h is the DSL PHY firmware embedded in IOS-XE Software Release X3.14.

Platform Support:

Platform	Maximum number of NIMs	Split of on-board NIM slots and NIM slots on SM-X carrier card
ISR4451	5	3 NIM slots + 2 * 1 NIM slot on each SM adaptor (2 SM slots)
ISR4431	3	Only NIM slots. No SM slots supported.
ISR4351	5	3 NIM slots + 2 * 1 NIM slot on each SM adaptor (2 SM slots)
ISR4331	3	2 NIM slots + 1 * 1 NIM slot on SM adaptor (1 SM slot)
ISR4321	2	Only NIM slots. No SM slots supported.

1.1. Variants of xDSL NIMs

Below are 3 variants of VDSL2/ADSL2+ NIMs:

Table 1.1. xDSL SKUs

Product Number	Description with Capabilities
NIM-VAB-A	1-port (2-pair) VDSL2/ADSL2+ NIM over POTS <ul style="list-style-type: none">• VDSL2 over POTS Band Plans<ul style="list-style-type: none">◦ VDSL2 profiles: 8a, 8b, 8c, 8d, 12a, 12b, 17a◦ VDSL2 bonding (of pair 0 and pair 1)◦ Profile 30a (over pair 1)◦ Vectoring• ADSL1/2/2+ Annex A, ADSL2 Annex L, non-optimized ADSL2/2+ Annex M
NIM-VAB-M	1-port (2-pair) VDSL2/ADSL2+ NIM over POTS with Annex M <ul style="list-style-type: none">• VDSL2 over POTS Band Plans<ul style="list-style-type: none">◦ VDSL2 profiles: 8a, 8b, 8c, 8d, 12a, 12b, 17a◦ VDSL2 bonding (of pair 0 and pair 1)◦ Profile 30a (over pair 1)◦ Vectoring• ADSL2/2+ Annex M, non-optimized ADSL/ADSL2/2+ Annex A
NIM-VA-B	1-port (1-pair) VDSL2/ADSL2+ NIM over ISDN <ul style="list-style-type: none">• ADSL1/2/2+ Annex B, non-optimized ADSL2/2+ Annex J• VDSL2 over ISDN Band Plans (8a to 17a) with Vectoring

1.2. DSL Feature Specifications

Table 1.2. DSL Specifications

DSL Specifications	
Multimode DSL (VDSL2 and	<ul style="list-style-type: none">• Broadcom chipset• One RJ-14 VDSL2 interface• Independent module firmware subpackage loading• Dying gasp

ADSL2/2+)	<ul style="list-style-type: none"> • Support for double-ended line testing (DELT) diagnostics mode • VDSL2: <ul style="list-style-type: none"> ◦ ITU G.993.2 (VDSL2) and ITU G.993.5 (VDSL2) ◦ 997 and 998 band plans ◦ VDSL2 profiles: 8a, 8b, 8c, 8d, 12a, 12b, and 17a ◦ VDSL bonding, Profile 30a and Vectoring ◦ U0 band support (25 to 276 kHz) ◦ Ethernet packet transfer mode (PTM) based only on IEEE 802.3ah 64/65 octet encapsulation ◦ TR114 ◦ DPBO ◦ INP • ADSL2/2+: <ul style="list-style-type: none"> ◦ ADSL over POTS with Annex A and Annex B ITU G. 992.1 (ADSL), G.992.3 (ADSL2), and G.992.5 (ADSL2+) ◦ ADSL over POTS with Annex M (extended upstream bandwidth) G.992.3 (ADSL2) and G.992.5 (ADSL2+) ◦ G.994.1 ITU G.hs ◦ Reach-extended ADSL2 (G.922.3) Annex L for increased performance on loop lengths greater than 16,000 feet from central office ◦ T1.413 ANSI ADSL DMT issue 2 compliance ◦ DSL Forum TR-067, and TR-100 conformity ◦ Impulse noise protection (INP) and extended INP ◦ Downstream power backoff (DPBO) ◦ Asynchronous transfer mode (ATM) only ◦ Maximum 8 PVCs per interface
------------------	--

2. Configuring DSL

By default operating mode auto in single-wire line 0 is enabled on the NIM.

```
controller VDSL 0/<slot>/<subslot>
  operating mode auto
```

2.1. Configuring ADSL

```
controller VDSL 0/<slot>/<subslot>
  operating mode <adsl1 or adsl2 or adsl2+>
```

2.2. Configuring VDSL2

2.2.1. VDSL2 Single-wire (8a to 17a)

Configuration of single-wire line 0 (pair 0) in VDSL2 mode:

```
controller VDSL 0/<slot>/<subslot>
operating mode VDSL2
line-mode single-wire line 0
```

Configuration of single-wire line 1 (pair 1) in VDSL2 mode:

```
controller VDSL 0/<slot>/<subslot>
operating mode VDSL2
line-mode single-wire line 1
```

2.2.2. VDSL2 30a profile

30a profile is supported only on line 1 (pair 1).

```
controller VDSL 0/<slot>/<subslot>
operating mode VDSL2
line-mode single-wire line 1 profile 30a
```

2.2.3. VDSL2 Bonding

Pair 0 and Pair 1 can be bonded in VDSL2 mode. You can configure bonding either in **auto** mode or **VDSL2**. The default configuration is **auto**.

```
controller vds1 0/<slot>/<subslot>
operating mode VDSL2
line-mode bonding
```

2.3. DSL configuration restrictions

- ADSL mode is supported only on Pair 0.

The following restrictions are applicable to VDSL2 bonding on the xDSL NIMs:

- VDSL2 bonding is supported only on NIM-VAB-A and NIMVAB-M.
- 30a profile is supported only on NIM-VAB-A and NIM-VAB-M.
- Even though NIM-VAB-A and NIMVAB-M support bonding, bonding is not the default configuration. The ADSL mode and VDSL single-wire mode are supported in the default configuration. User should enable bonding using the **line-mode bonding** command.
- **no line-mode bonding** and **default line-mode bonding** commands change the configuration to 'single-wire' on Line 0, which is the default configuration.
- The line-mode configuration is removed from the Router whenever operating mode is changed and it should be configured again when the operating mode is re-configured.

2.4. DSL configuration examples

The following example shows how to enable VDSL2 bonding in auto mode:

```
Router# configure terminal  
Router(config)# controller vdsl 0/1/0  
Router(config-controller)# operating mode auto  
Router(config-controller)# line-mode bonding  
Router(config-controller)# exit
```

The following example shows how to enable VDSL2 bonding in VDSL2 mode:

```
Router# configure terminal  
Router(config)# controller vdsl 0/1/0  
Router(config-controller)# operating mode vdsl2  
Router(config-controller)# line-mode bonding  
Router(config-controller)# exit
```

The following example shows how to remove bonding:

```
Router# configure terminal  
Router(config)# controller vdsl 0/1/0  
Router(config-controller)# no line-mode bonding  
Router(config-controller)# no operating mode  
Router(config-controller)# exit
```

The following example shows how to enable profile 8a through 17a on line 0 in auto mode:

```
Router# configure terminal  
Router(config)# controller vdsl 0/1/0  
Router(config-controller)# line-mode single-wire line 0  
Router(config-controller)# exit
```

The following example shows how to enable profile 30a on line 1:

```
Router# configure terminal  
Router(config)# controller vdsl 0/1/0  
Router(config-controller)# operating mode vdsI2  
Router(config-controller)# line-mode single-wire line 1 profile 30a  
Router(config-controller)# exit
```

The following example shows how to remove profile 30a from line 1:

```
Router# configure terminal  
Router(config)# controller vdsl 0/1/0  
Router(config-controller)# no line-mode single-wire line 1  
Router(config-controller)# no operating mode vdsI2  
Router(config-controller)# exit
```

3. Features supported in IOS-XE 3.14 over xDSL NIMs

3.1. Firmware upgrade and downgrade

This feature would help the users to get the DSL module firmware fixes immediately by moving to new module firmware, instead of waiting for the next IOS release to get the fixes. Fixes in module firmware would be posted on CCO as .pkg subpackage file.

Prerequisite:

Router should be booted up in packages.conf mode with the IOS-XE image (Super Package) during installation period so that as and when required firmware could be upgraded or downgraded without reloading the Router.

1. Copy IOS_XE image to **bootflash:mydir**
2. **request platform software package expand file boot flash:/mydir/<IOS-XE image>** to expand super package.
3. Go to Router rommon mode.
4. **boot bootflash:mydir/packages.conf**


```

CCCCCCCCCCCCCCCCCCCC
425288648 bytes copied in 44.826 secs (9487544 bytes/sec)
Router#
Router#
Router#dir bootflash:mydir
Directory of bootflash:/mydir/
632738 -rw- 425288648 Dec 12 2014 09:16:42 +00:00 isr4400-universalk9.03.14.00.S.155-1.S-
std.SPA.bin

7451738112 bytes total (474025984 bytes free)
Router#

```

Step 2: “request platform software package expand file bootflash:/mydir /<IOS-XE image>“ to expand super package.

```

Router#request platform software package expand file bootflash:/mydir/isr4400-
universalk9.03.14.00.S.155-1.S-std.SPA.bin
Verifying parameters
Validating package type
Copying package files
SUCCESS: Finished expanding all-in-one software package.
Router#

```

Step 3: Go to Router rommon mode.

```

Router#reload
Proceed with reload? [confirm]

```

```

*Dec 12 09:26:09.874: %SYS-5-RELOAD: Reload requested by console. Reload Reason: Reload
Command.Dec 12 09:26:25.156 R0/0: %PMAN-5-EXITACTION: Process manager is exiting: process exit with
reload chassis code

```

Initializing Hardware ...

System integrity status: 00000610

Rom image verified correctly

System Bootstrap, Version 15.3(3r)S1, RELEASE SOFTWARE
Copyright (c) 1994-2013 by cisco Systems, Inc.

Current image running: Boot ROM0

Last reset cause: LocalSoft

Cisco ISR4451-X/K9 platform with 4194304 Kbytes of main memory

Step 4: boot bootflash:mydir/packages.conf

rommon 1 > boot bootflash:mydir/packages.conf

File size is 0x000028f1

Located mydir/packages.conf

Image size

10481 inode num 632741, bks cnt 3 blk size 8*512

#

File size is 0x150ae3cc

Located mydir/isr4400-mono-universalk9.03.14.00.S.155-1.S-std.SPA.pkg

Image size 353035212 inode num 356929, bks cnt 86191 blk size 8*512

```
#####
#####
```

Boot image size = 353035212 (0x150ae3cc) bytes

```
Package header rev 1 structure detected

Calculating SHA-1 hash...done

validate_package: SHA-1 hash:

calculated 8e966678:8afb08f4:8a88bb8f:fe591121:8bddf4b3

expected 8e966678:8afb08f4:8a88bb8f:fe591121:8bddf4b3

RSA Signed RELEASE Image Signature Verification Successful.

Package Load Test Latency : 3799 msec

Image validated

Dec 12 09:28:50.338 R0/0: %FLASH_CHECK-3-DISK_QUOTA: Flash disk quota exceeded [free space is 61864 KB] - Please clean up files on bootflash.
```

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227-7013.

cisco Systems, Inc.
170 West Tasman Drive
San Jose, California 95134-1706

Cisco IOS Software, ISR Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version 15.5(1)S, RELEASE SOFTWARE (fc5)
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2014 by Cisco Systems, Inc.
Compiled Thu 20-Nov-14 18:28 by mcpree

Cisco IOS-XE software, Copyright (c) 2005-2014 by cisco Systems, Inc.
All rights reserved. Certain components of Cisco IOS-XE software are licensed under the GNU General Public License ("GPL") Version 2.0. The software code licensed under GPL Version 2.0 is free software that comes with ABSOLUTELY NO WARRANTY. You can redistribute and/or modify such GPL code under the terms of GPL Version 2.0. For more details, see the documentation or "License Notice" file accompanying the IOS-XE software, or the applicable URL provided on the flyer accompanying the IOS-XE software.

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
<http://www.cisco.com/wlc/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to export@cisco.com.

cisco ISR4451-X/K9 (2RU) processor with 1681388K/6147K bytes of memory.
Processor board ID FTX1736AJUT
2 Ethernet interfaces
4 Gigabit Ethernet interfaces
2 ATM interfaces
32768K bytes of non-volatile configuration memory.
4194304K bytes of physical memory.
7393215K bytes of flash memory at bootflash:..

Press RETURN to get started!

```
*Dec 12 09:28:58.922: %IOS_LICENSE_IMAGE_APPLICATION-6-LICENSE_LEVEL: Module name = esg Next
reboot level = appxk9 and License = appxk9
*Dec 12 09:28:58.943: %IOS_LICENSE_IMAGE_APPLICATION-6-LICENSE_LEVEL: Module name = esg Next
reboot level = ipbasek9 and License = ipbasek9
*Dec 12 09:28:58.981: %ISR_THROUGHPUT-6-LEVEL: Throughput level has been set to 1000000 kbps
*Dec 12 09:29:13.302: %SPANTREE-5-EXTENDED_SYSID: Extended SysId enabled for type vlan
*Dec 12 09:29:14.142: %LINK-3-UPDOWN: Interface Lsmpi0, changed state to up
*Dec 12 09:29:14.142: %LINK-3-UPDOWN: Interface EOBC0, changed state to up
*Dec 12 09:29:14.142: %LINK-3-UPDOWN: Interface GigabitEthernet0, changed state to down
*Dec 12 09:29:14.142: %LINK-3-UPDOWN: Interface LIINO, changed state to up
*Dec 12 09:28:51.438: %CMRP-3-PFU_MISSING:cmand: The platform does not detect a power supply in
slot 1
*Dec 12 09:29:01.256: %CMLIB-6-THROUGHPUT_VALUE:cmand: Throughput license found, throughput set
to 1000000 kbps
*Dec 12 09:29:03.223: %CPPHA-7-START:cpp_ha: CPP 0 preparing ucode
*Dec 12 09:29:03.238: %CPPHA-7-START:cpp_ha: CPP 0 startup init
*Dec 12 09:29:11.335: %CPPHA-7-START:cpp_ha: CPP 0 running init
*Dec 12 09:29:11.645: %CPPHA-7-READY:cpp_ha: CPP 0 loading and initialization complete
*Dec 12 09:29:11.711: %IOSXE-6-PLATFORM:cpp_cp: Process
CPP_PFILTER_EA_EVENT__API_CALL__REGISTER
*Dec 12 09:29:16.280: %IOSXE_MGMTVRF-6-CREATE_SUCCESS_INFO: Management vrf Mgmt-intf created
with ID 1, ipv4 table-id 0x1, ipv6 table-id 0x1E000001
*Dec 12 09:29:16.330: %LINEPROTO-5-UPDOWN: Line protocol on Interface Lsmpi0, changed state to up
*Dec 12 09:29:16.330: %LINEPROTO-5-UPDOWN: Line protocol on Interface EOBC0, changed state to up
*Dec 12 09:29:16.330: %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0, changed
state to down
*Dec 12 09:29:16.330: %LINEPROTO-5-UPDOWN: Line protocol on Interface LIINO, changed state to up
*Dec 12 09:29:17.521: %SYS-5-LOG_CONFIG_CHANGE: Buffer logging disabled
*Dec 12 09:29:18.867: %SYS-5-CONFIG_I: Configured from memory by console
*Dec 12 09:29:18.870: %IOSXE_OIR-6-REMSPA: SPA removed from subslot 0/0, interfaces disabled
*Dec 12 09:29:18.870: %IOSXE_OIR-6-REMSPA: SPA removed from subslot 0/1, interfaces disabled
*Dec 12 09:29:18.871: %IOSXE_OIR-6-REMSPA: SPA removed from subslot 0/2, interfaces disabled
```

```

*Dec 12 09:29:18.873: %SPA_OIR-6-OFFLINECARD: SPA (ISR4451-X-4x1GE) offline in subslot 0/0
*Dec 12 09:29:18.874: %SPA_OIR-6-OFFLINECARD: SPA (NIM-VA-B) offline in subslot 0/1
*Dec 12 09:29:18.874: %SPA_OIR-6-OFFLINECARD: SPA (NIM-VAB-A) offline in subslot 0/2
*Dec 12 09:29:18.876: %IOSXE_OIR-6-INSCARD: Card (fp) inserted in slot F0
*Dec 12 09:29:18.876: %IOSXE_OIR-6-ONLINECARD: Card (fp) online in slot F0
*Dec 12 09:29:18.882: %IOSXE_OIR-6-INSSPA: SPA inserted in subslot 0/0
*Dec 12 09:29:18.884: %IOSXE_OIR-6-INSSPA: SPA inserted in subslot 0/1
*Dec 12 09:29:18.884: %IOSXE_OIR-6-INSSPA: SPA inserted in subslot 0/2
*Dec 12 09:29:18.935: %SYS-5-RESTART: System restarted --
Cisco IOS Software, ISR Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version 15.5(1)S, RELEASE
SOFTWARE (fc5)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2014 by Cisco Systems, Inc.
Compiled Thu 20-Nov-14 18:28 by mcpre
*Dec 12 09:29:18.895: %SPA-3-ENVMON_NOT_MONITORED:iomd: Environmental monitoring is not
enabled for ISR4451-X-4x1GE[0/0]
*Dec 12 09:29:19.878: %LINK-5-CHANGED: Interface GigabitEthernet0, changed state to administratively
down
*Dec 12 09:29:22.419: %SPA_OIR-6-ONLINECARD: SPA (ISR4451-X-4x1GE) online in subslot 0/0
*Dec 12 09:29:22.610: %SYS-6-BOOTTIME: Time taken to reboot after reload = 194 seconds
*Dec 12 09:29:24.354: %LINK-3-UPDOWN: Interface GigabitEthernet0/0/0, changed state to down
*Dec 12 09:29:24.415: %LINK-3-UPDOWN: Interface GigabitEthernet0/0/2, changed state to down
*Dec 12 09:29:24.417: %LINK-3-UPDOWN: Interface GigabitEthernet0/0/3, changed state to down
*Dec 12 09:29:30.919: %LINK-3-UPDOWN: Interface GigabitEthernet0/0/0, changed state to up
*Dec 12 09:29:30.925: %LINK-3-UPDOWN: Interface GigabitEthernet0/0/2, changed state to up
*Dec 12 09:29:30.936: %LINK-3-UPDOWN: Interface GigabitEthernet0/0/3, changed state to up
*Dec 12 09:29:31.919: %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0/0/0, changed
state to up
*Dec 12 09:29:31.930: %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0/0/2, changed
state to up
*Dec 12 09:29:31.936: %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0/0/3, changed
state to up
*Dec 12 09:29:34.147: %SSH-5-ENABLED: SSH 1.99 has been enabled
*Dec 12 09:30:29.152: %SPA_OIR-6-ONLINECARD: SPA (NIM-VA-B) online in subslot 0/1
*Dec 12 09:30:29.470: %SPA_OIR-6-ONLINECARD: SPA (NIM-VAB-A) online in subslot 0/2
*Dec 12 09:30:31.152: %LINK-3-UPDOWN: Interface Ethernet0/1/0, changed state to down
*Dec 12 09:30:31.152: %LINK-3-UPDOWN: Interface ATM0/1/0, changed state to down
*Dec 12 09:30:31.470: %LINK-3-UPDOWN: Interface Ethernet0/2/0, changed state to down
*Dec 12 09:30:31.470: %LINK-3-UPDOWN: Interface ATM0/2/0, changed state to down
*Dec 12 09:31:03.074: %CONTROLLER-5-UPDOWN: Controller VDSL 0/2/0, changed state to up
*Dec 12 09:31:05.075: %LINK-3-UPDOWN: Interface Ethernet0/2/0, changed state to up
*Dec 12 09:31:06.076: %LINEPROTO-5-UPDOWN: Line protocol on Interface Ethernet0/2/0, changed state
to up
*Dec 12 09:31:12.559: %CONTROLLER-5-UPDOWN: Controller VDSL 0/1/0, changed state to up
*Dec 12 09:31:20.188: %LINK-3-UPDOWN: Interface ATM0/1/0, changed state to up
*Dec 12 09:31:21.188: %LINEPROTO-5-UPDOWN: Line protocol on Interface ATM0/1/0, changed state to up
Router>
Router>en
Password:
Router#
Router#show controller vdsl 0/2/0
Controller VDSL 0/2/0 is UP

```

Daemon Status: UP

	XTU-R (DS)	XTU-C (US)
Chip Vendor ID:	'BDCM'	'BDCM'
Chip Vendor Specific:	0x0000	0xA41B

Chip Vendor Country: 0xB500 0xB500
 Modem Vendor ID: 'CSCO' ''
 Modem Vendor Specific: 0x4602 0x0000
 Modem Vendor Country: 0xB500 0x0000
 Serial Number Near: FOC18426DQ8 4451-X/K15.5(1)S
 Serial Number Far:
 Modem Version Near: 15.5(1)S
 Modem Version Far: 0xa41b

Modem Status(L1): TC Sync (Showtime!)
 DSL Config Mode: VDSL2
 Trained Mode(L1): G.993.2 (VDSL2) Profile 30a

TC Mode: PTM
 Selftest Result: 0x00
 DELT configuration: disabled
 DELT state: not running

Failed full inits: 0
 Short inits: 0
 Failed short inits: 0

Modem FW Version: 4.14L.04
 Modem PHY Version: A2pv6F039h.d24o_rc1

Line 1:

	XTU-R (DS)		XTU-C (US)				
Trellis:	ON		ON				
SRA:	disabled		disabled				
SRA count:	0		0				
Bit swap:	enabled		enabled				
Bit swap count:	9		0				
Profile 30a:	enabled						
Line Attenuation:	3.5 dB	0.0 dB					
Signal Attenuation:	0.0 dB	0.0 dB					
Noise Margin:	30.9 dB	12.4 dB					
Attainable Rate:	200000 kbytes/s	121186 kbytes/s					
Actual Power:	13.3 dBm	7.2 dBm					
Per Band Status:	D1	D2	D3	U0	U1	U2	U3
Line Attenuation(dB):	0.9	1.5	5.5	N/A	0.1	0.9	3.8
Signal Attenuation(dB):	0.8	1.5	5.5	N/A	0.0	0.2	3.2
Noise Margin(dB):	31.1	31.0	30.9	N/A	12.3	12.4	12.5
Total FECC:	0		0				
Total ES:	0		0				
Total SES:	0		0				
Total LOSS:	0		0				
Total UAS:	51		51				
Total LPRS:	0		0				
Total LOFS:	0		0				
Total LOLS:	0		0				

	DS Channel1	DS Channel0	US Channel1	US Channel0
Speed (kbps):	NA	100014	NA	100014
SRA Previous Speed:	NA	0	NA	0
Previous Speed:	NA	0	NA	0
Reed-Solomon EC:	NA	0	NA	0

CRC Errors:	NA	0	NA	0	
Header Errors:		NA	0	NA	0
Interleave (ms):	NA	9.00		NA	0.00
Actual INP:	NA	4.00		NA	0.00

Training Log : Stopped
 Training Log Filename : flash:vdslog.bin

Router#
 Router#

Step 5: Copy NIM firmware subpackage to the folder bootflash:/mydir

```
Router#copy bootflash:isr4400-firmware_nim_xdsl.2014-11-17_11.05_39n.SSA.pkg
bootflash:mydir/
Destination filename [mydir/isr4400-firmware_nim_xdsl.2014-11-17_11.05_39n.SSA.pkg]?
Copy in
progress...CCCCCCCCCC...CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
6640604 bytes copied in 1.365 secs (4864911 bytes/sec)
Router#
```

Step 6: “ request platform software package install rp 0 file bootflash:/mydir/<firmware subpackage> “

```
Router#request platform software package install rp 0 file bootflash:mydir/isr4400-
firmware_nim_xdsl.2014-11-17_11.05_39n.SSA.pkg
--- Starting local lock acquisition on R0 ---
Finished local lock acquisition on R0

--- Starting file path checking ---
Finished file path checking

--- Starting image file verification ---
Checking image file names
Locating image files and validating name syntax
Found isr4400-firmware_nim_xdsl.2014-11-17_11.05_39n.SSA.pkg
Verifying image file locations
Inspecting image file types
Processing image file constraints
Creating candidate provisioning file
Finished image file verification

--- Starting candidate package set construction ---
Verifying existing software set
Processing candidate provisioning file
Constructing working set for candidate package set
Constructing working set for running package set
Checking command output
Constructing merge of running and candidate packages
Checking if resulting candidate package set would be complete
Finished candidate package set construction

--- Starting ISSU compatibility verification ---
Verifying image type compatibility
Checking IPC compatibility with running software
```

```
Checking candidate package set infrastructure compatibility
Checking infrastructure compatibility with running software
Checking package specific compatibility
Finished ISSU compatibility verification

--- Starting impact testing ---
Checking operational impact of change
Finished impact testing

--- Starting list of software package changes ---
Old files list:
    Removed isr4400-firmware_nim_xdsl.03.14.00.S.155-1.S-std.SPA.pkg
New files list:
    Added isr4400-firmware_nim_xdsl.2014-11-17_11.05_39n.SSA.pkg
Finished list of software package changes

--- Starting commit of software changes ---
Updating provisioning rollback files
Creating pending provisioning file
Committing provisioning file
Finished commit of software changes

--- Starting analysis of software changes ---
Finished analysis of software changes

--- Starting update running software ---
Blocking peer synchronization of operating information
Creating the command set placeholder directory
    Finding latest command set
    Finding latest command shortlist lookup file
    Finding latest command shortlist file
    Assembling CLI output libraries
    Assembling CLI input libraries
    Skipping soft links for firmware upgrade
    Skipping soft links for firmware upgrade
    Assembling Dynamic configuration files
    Applying interim IPC and database definitions
rsync: getaddrinfo: cc2-0 873: Name or service not known rsync error: error in socket IO (code 10) at
/auto/mcpbuilds19/release/03.14.00.S/BLD-V03_14_00_S_FC5/contrib/rsync/clientserver.c(104)
[sender=2.6.9]
rsync: getaddrinfo: cc2-0 873: Name or service not known rsync error: error in socket IO (code 10) at
/auto/mcpbuilds19/release/03.14.00.S/BLD-V03_14_00_S_FC5/contrib/rsync/clientserver.c(104)
[sender=2.6.9]
rsync: getaddrinfo: cc2-0 873: Name or service not known rsync error: error in socket IO (code 10) at
/auto/mcpbuilds19/release/03.14.00.S/BLD-V03_14_00_S_FC5/contrib/rsync/clientserver.c(104)
[sender=2.6.9]
    Replacing running software
    Replacing CLI software
    Restarting software
    Applying final IPC and database definitions
rsync: getaddrinfo: cc2-0 873: Name or service not known rsync error: error in socket IO (code 10) at
/auto/mcpbuilds19/release/03.14.00.S/BLD-V03_14_00_S_FC5/contrib/rsync/clientserver.c(104)
[sender=2.6.9]
    Generating software version information
    Notifying running software of updates
    Unblocking peer synchronization of operating information
Unmounting old packages
Cleaning temporary installation files
```

```

Finished update running software

SUCCESS: Finished installing software.
Router#
Router#show platform software subslot 0/2 module firmware
Avg Load info
-----
1.83 1.78 1.44 3/45 607

Kernel distribution info
-----
Linux version 3.4.11-rt19 (sapanwar@blr-atg-001) (gcc version 4.6.2 (Buildroot 2011.11) ) #3 SMP PREEMPT
Fri Nov 7 09:26:19 IST 2014

Module firmware versions
-----
Modem Fw Version: 4.14L.04
Modem Phy Version: A2pv6F039h.d24o_rc1

Boot Loader: Secondary
-----
Version: 1.1

Modem Up time
-----
0D 0H 25M 38S

Router#

```

Step 7: “hw-module subslot x/y reload “ to boot the module with the new firmware.

```

Router#hw-module subslot 0/2 reload
Proceed with reload of module? [confirm]
Router#
*Dec 12 09:55:59.645: %IOSXE_OIR-6-SOFT_RELOADSPA: SPA(NIM-VAB-A) reloaded on subslot 0/2
*Dec 12 09:55:59.646: %SPA_OIR-6-OFFLINECARD: SPA (NIM-VAB-A) offline in subslot 0/2
*Dec 12 09:55:59.647: %CONTROLLER-5-UPDOWN: Controller VDSL 0/2/0, changed state to down
*Dec 12 09:57:22.514: new extended attributes received from iomd(slot 0 bay 2 board 0)
*Dec 12 09:57:22.514: %IOSXE_OIR-6-SOFT_RELOADSPA: SPA(NIM-VAB-A) reloaded on subslot 0/2
*Dec 12 09:57:22.515: %SPA_OIR-6-OFFLINECARD: SPA (NIM-VAB-A) offline in subslot 0/2
Router#
Router#
*Dec 12 09:58:35.471: %SPA_OIR-6-ONLINECARD: SPA (NIM-VAB-A) online in subslot 0/2
*Dec 12 09:58:37.470: %LINK-3-UPDOWN: Interface Ethernet0/2/0, changed state to down
*Dec 12 09:58:37.470: %LINK-3-UPDOWN: Interface ATM0/2/0, changed state to down
Router#

```

Step 8: Verify module is booted up with new firmware

```
Router#show platform software subslot 0/2 module firmware
```

```

Avg Load info
-----
0.84 0.23 0.08 1/45 598

Kernel distribution info

```

```

-----
Linux version 3.4.11-rt19 (sapanwar@blr-atg-001) (gcc version 4.6.2 (Buildroot 2011.11) ) #6 SMP PREEMPT
Mon Nov 17 10:51:41 IST 2014

Module firmware versions
-----
Modem Fw Version: 4.14L.04
Modem Phy Version: A2pv6F039n.d24o_rc1

Boot Loader: Secondary
-----
Version: 1.1

Modem Up time
-----
0D 0H 0M 42S

Router#

```

3.2. Dynamic Bandwidth Change for ATM PVCs

The ATM Dynamic Bandwidth for ATM PVCs over DSL feature provides the ability to configure Cisco IOS-XE software to automatically adjust PVC bandwidth in response to changes in the total available interface bandwidth. This feature eliminates the manual intervention every time DSL line rate changes, and allows the available bandwidth to be used effectively at all times.

Restrictions for Implementing ATM Dynamic Bandwidth

- This feature is supported only for ATM permanent virtual circuits (PVCs).
- The algorithm used to implement this feature is applied only when dynamic changes to ATM interface occur. It is applied at VC creation on Router bootup as well.
- If the ATM Dynamic Bandwidth feature is enabled/disabled after a change in total bandwidth, feature would not work until line toggles.

How to Enable ATM Dynamic Bandwidth

By default atm dynamic bandwidth feature is enabled.

If atm dynamic bandwidth is disabled, below are the steps to enable the feature.

*Router#conf t
Enter configuration commands, one per line. End with CNTL/Z.*

```

Router(config)#int atm0/1/0
Router(config-if)#atm bandwidth dynamic
Router(config-if)#end
Router#

```

Sample configuration:

```

!
interface ATM0/1/0
no ip address
load-interval 30
no atm enable-ilmi-trap
!
```

Show atm pvc output with atm dynamic bandwidth enabled.

Example 1:

```

Router#show atm pvc
      VCD /          Peak Av/Min Burst
Interface Name    VPI  VCI Type  Encaps   SC   Kbps  Kbps Cells St
0/1/0.1       1     8  37 PVC    MUX    UBR  1045           UP
                                         (C)  UBR    0
Router#

```

Example 2:

```

Router#show atm pvc
      VCD /          Peak Av/Min Burst
Interface Name    VPI  VCI Type  Encaps   SC   Kbps  Kbps Cells St
0/3/0.1       2     0  32 PVC    SNAP   CBR  294           UP
                                         (C)  CBR    300

```

Note: (C) is the configured rates.

In example 2, CBR pvc was configured with PCR as 300 kbps. Due to line rate change, pcr rate has dynamically changed to 294kbps.

How to Disable ATM Dynamic Bandwidth

```

Router#conf t
Enter configuration commands, one per line. End with CNTL/Z.
Router(config)#int atm0/1/0
Router(config-if)#no atm bandwidth dynamic
Router(config-if)#end
Router#

```

```
Router#sh run int atm0/1/0
Building configuration...

Current configuration : 110 bytes
!
interface ATM0/1/0
no ip address
load-interval 30
no atm bandwidth dynamic
no atm enable-ilmi-trap
end
```

Router#

Show atm pvc output with atm dynamic bandwidth feature disabled:

```
Router#show atm pvc | sec 0/1/0
0/1/0.1 1      8  37 PVC   MUX    UBR  1045      UP
Router#
```

Usage Guidelines

Dynamic bandwidth management is supported on all PVC service classes.

If necessary and applicable for a particular PVC based on its service class, new values are applied for the following parameters when PVCs are re-created:

- peak cell rate (PCR)—all supported Service classes
- sustainable cell rate (SCR)— VBR Service classes

How the ATM Dynamic Bandwidth Feature Works

When the total available bandwidth on a DSL interface changes, all of the PVCs configured under the ATM sub-interface(s) are re-created.

If necessary and applicable for a particular PVC based on its service class, new values are applied for the following parameters when PVCs are re-created:

- PCR—peak cell rate
- SCR—sustainable cell rate

The following steps are performed by the Cisco IOS-XE software to determine what value should be assigned to a parameter when a PVC is re-created in response to a change in total available bandwidth:

- A value is calculated for the parameter. The calculation takes into account the configured value for the parameter, the active value for the parameter (if it is different from the configured value), and the change in total available bandwidth.
- The calculated value is compared to the configured value of the parameter and to the maximum available cell rate, and a new value is determined. The new value is applied when the PVC is re-created.

The following sections describe how the new parameter values are determined when a PVC is re-created for supported QoS classes:

CBR PVCs

When the total available bandwidth changes, PVCs configured with CBR service class are re-created as follows:

- If the configured PCR value is less than the calculated PCR value, the PVC is re-created with the configured PCR value.
- If the configured PCR value is greater than the calculated PCR value, the PVC is re-created as UBR PVC with a PCR value equal to the maximum available rate

VBR PVCs

When the total available bandwidth changes, PVCs configured with VBR service class are re-created as follows:

- If the configured PCR value is less than the calculated PCR value, the PVC is re-created with the configured PCR value.
- If the configured PCR value is greater than the calculated PCR value, the PVC is re-created with a new PCR value. The new PCR value will be the lower of the following values:
 - The calculated PCR value
 - The maximum available cell rate
- If the configured SCR value is less than the calculated PCR value, the PVC is re-created with the configured SCR value.

- If the configured SCR value is greater than the calculated PCR value, the PVC is re-created with a new SCR value. The new SCR value will be the lower of the following values:
 - The calculated PCR value
 - The maximum available cell rate

UBR PVCs

When the total available bandwidth changes, PVCs configured with UBR service class are re-created as follows:

- If the PCR configuration is set to the default, the PVC is re-created with a PCR value equal to the new line rate.
- If the configured PCR value is less than the calculated PCR value, the PVC is re-created with the configured PCR value.
- If the configured PCR value is greater than the calculated PCR value, the PVC is re-created with a new PCR value. The new PCR value will be the lower of the following values:
 - The calculated PCR value
 - New line rate

Example:

Below is the example for the sum of pvc rates less than the line rate of 1561kbps.

Router#show atm pvc

Interface	Name	Peak Av/Min Burst					
		VPI	VCI	Type	Encaps	SC	Kbps Cells St
0/3/0.1	2	0	32	PVC	SNAP	CBR	300 (C) CBR 300
0/3/0.2	3	0	33	PVC	SNAP	CBR	100 (C) CBR 100
0/3/0.3	4	0	34	PVC	SNAP	VBR	400 200 10 UP (C) VBR 400 200 10
0/3/0.4	5	0	35	PVC	SNAP	VBR	600 300 10 UP (C) VBR 600 300 10
0/3/0.5	6	0	36	PVC	SNAP	VBR	300 150 10 UP (C) VBR 300 150 10
0/3/0.6	7	0	37	PVC	SNAP	VBR	700 450 10 UP (C) VBR 700 450 10
0/3/0.7	8	0	38	PVC	SNAP	UBR	1561 (C) UBR 0
0/3/0.8	1	0	39	PVC	SNAP	UBR	1000 (C) UBR 1000

When line rate gets downgraded to 687kbps, CBR and VBR PVC rates gets adjusted dynamically as below.

Router#show atm pvc

		VCD /		Peak Av/Min Burst				
Interface	Name	VPI	VCI	Type	Encaps	SC	Kbps	Kbps Cells St
0/3/0.1	2	0	32	PVC	SNAP	CBR	300	UP (C) CBR 300
0/3/0.2	3	0	33	PVC	SNAP	CBR	100	UP (C) CBR 100
0/3/0.3	4	0	34	PVC	SNAP	VBR	287	200 10 UP (C) VBR 400 200 10
0/3/0.4	5	0	35	PVC	SNAP	VBR	87	87 1 UP (C) VBR 600 300 10
0/3/0.5	6	0	36	PVC	SNAP	UBR	687	UP (C) VBR 300 150 10
0/3/0.6	7	0	37	PVC	SNAP	UBR	687	UP (C) VBR 700 450 10
0/3/0.7	8	0	38	PVC	SNAP	UBR	687	UP (C) UBR 0
0/3/0.8	1	0	39	PVC	SNAP	UBR	687	UP (C) UBR 1000

3.3. ATM Oversubscription for DSL

The ATM Oversubscription for DSL feature enables users to improve network utilization of otherwise underutilized shared networks by leveraging statistical multiplexing on ATM networks. Instead of supporting only unconditional reservation of network bandwidth to VBR PVCs, the Router offers PVC oversubscription to statistically guarantee bandwidth to VBR PVCs.

In Cisco IOS-XE Software Release XE3.14 or later, the ATM Oversubscription feature enables you to specify the amount of oversubscription (oversubscription factor) equal to twice the line rate.

Following are the features of oversubscription

- Oversubscription is allowed on VBR-rt and VBR-nrt.
- Under no over subscription condition, PVCs can be configured up to line rate. For example, if the line rate is 1000 Kbps. The SCR or PCR of a VBR PVC cannot be more than 1000 Kbps if there are no other PVCs. If there is a CBR PVC with PCR of 500Kbps, then the maximum SCR or PCR allowed on the VBR PVC is 500 Kbps.
- When over-subscription is enabled, multiple VBR-rt or VBR-nrt PVCs are allowed to be configured even if the sum of their SCRs exceeds the actual bandwidth available over the physical line. Suppose oversubscription is enabled and over subscription

factor of 2 is set for a line rate of 1000k sum of SCRs of VBR-rt and VBR-nrt can be less than or equal to 2000k, this is excluding CBR PVCs bandwidth.

- If the user configures VBR-rt or VBR-nrt more than the configured oversubscription factor then PVC will be configured for the bandwidth available. If there is no oversubscription bandwidth left then VC will be downgraded to UBR. For example for line rate of 1000k, with oversubscription factor 2: PVC1 is vbr-rt 400k 400k, PVC2 is vbr-nrt 1600k 1600k and PVC3 is vbr-rt 500k 500k. In this case the PVC1 and PVC2 will be configured to given pcr and scr, PVC3 will be downgraded to UBR class.
- If there is no bandwidth left , then some PVCs may be downgraded to UBR class.

Oversubscription of the ATM interfaces is enabled by default and is subject to infinite oversubscription factor which is not supported on DSL NIM. User must enable oversubscription factor.

The following configuration enables the oversubscription 2. The only oversubscription factor supported is 2.

```
Router(config)# interface atm 0/1/0
Router(config-if)# atm oversubscription factor 2
Router(config-if)# exit
```

To disable oversubscription of the interface, use the no atm oversubscribe command.

For example, the following configuration disables oversubscription of the ATM 0/1/0 interface

```
Router(config)# interface atm 0/1/0
Router(config-if)# no atm oversubscribe
Router(config-if)# exit
```

Example:

Below is the example for the sum of pvc rates less than the line rate of 1561kbps.

```
Router#show atm pvc
```

		VCD /	Peak Av/Min Burst							
Interface	Name	VPI	VCI	Type	Encaps	SC	Kbps	Kbps	Cells	St
0/3/0.1	2	0	32	PVC	SNAP	CBR	300		UP	
				(C)	CBR		300			
0/3/0.2	3	0	33	PVC	SNAP	CBR	100		UP	
				(C)	CBR		100			
0/3/0.3	4	0	34	PVC	SNAP	VBR	400	200	10	UP

			(C)	VBR	400	200	10		
0/3/0.4	5	0	35 PVC	SNAP	VBR	600	300	10 UP	
			(C)	VBR	600	300	10		
0/3/0.5	6	0	36 PVC	SNAP	VBR	300	150	10 UP	
			(C)	VBR	300	150	10		
0/3/0.6	7	0	37 PVC	SNAP	VBR	700	450	10 UP	
			(C)	VBR	700	450	10		
0/3/0.7	8	0	38 PVC	SNAP	UBR	1561		UP	
			(C)	UBR	0				
0/3/0.8	1	0	39 PVC	SNAP	UBR	1000		UP	
			(C)	UBR	1000				

When line rate gets downgraded to 294kbps, CBR and VBR PVC rates gets adjusted dynamically as below.

Router#show atm pvc

VCD /			Peak Av/Min Burst						
Interface	Name	VPI	VCI	Type	Encaps	SC	Kbps	Kbps Cells St	
0/3/0.1	2	0	32 PVC	SNAP	CBR	294		UP	
			(C)	CBR	300				
0/3/0.2	3	0	33 PVC	SNAP	UBR	294		UP	
			(C)	CBR	100				
0/3/0.3	4	0	34 PVC	SNAP	VBR	294	200	10 UP	
			(C)	VBR	400	200	10		
0/3/0.4	5	0	35 PVC	SNAP	VBR	294	294	1 UP	
			(C)	VBR	600	300	10		
0/3/0.5	6	0	36 PVC	SNAP	VBR	94	94	1 UP	
			(C)	VBR	300	150	10		
0/3/0.6	7	0	37 PVC	SNAP	UBR	294		UP	
			(C)	VBR	700	450	10		
0/3/0.7	8	0	38 PVC	SNAP	UBR	294		UP	
			(C)	UBR	0				
0/3/0.8	1	0	39 PVC	SNAP	UBR	294		UP	
			(C)	UBR	1000				

3.4. Multilink PPP (MLPPP) bundling

3.4.1. Multilink PPP Minimum Links Mandatory

3.4.2. MLPPP bundling of interfaces

3.4.3. ATM Multilink PPP Support on Multiple VCs

Reference doc : http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/wan_mlp/configuration/xe-3s/wan-mlp-xe-3s-book/wan_cfg_mlppp_conn_xe.html

http://www.cisco.com/en/US/docs/ios/atm/configuration/guide/atm_ml_pmul_vc.html

3.5. ATM Routed Bridge Encapsulation (RBE)

Reference doc: <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/bbdsi/configuration/xe-3s/bba-xe-3s-book/bba-atm-rbe-xe.html>

<http://www.cisco.com/c/en/us/support/docs/long-reach-ethernet-lre-digital-subscriber-line-xdsl/asymmetric-digital-subscriber-line-adsl/12917-routed-bridged-encap.html>

3.6. RBE Client Side Encapsulation with QoS

Reference doc:

http://www.cisco.com/c/en/us/td/docs/ios/12_4t/12_4t2/htrbegos.html

<http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/bbdsi/configuration/15-mt/bba-15-mt-book/bba-csencap-qos.html>

http://www.cisco.com/c/en/us/td/docs/ios/12_4t/12_4t2/htrbegos.html

3.7. ATM Cell Loss Priority (CLP) Bit Marking

Reference doc: http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_mqc/configuration/xe-3s/qos-mqc-xe-3s-book/qos-atm-clp.html

3.8. ATM Cell Loss Priority (CLP) Setting

Reference doc: http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_mqc/configuration/xe-3s/qos-mqc-xe-3s-book/qos-atm-clp.html

3.9. ATM OAM Loopback Mode Detection

Reference doc:

http://www.cisco.com/c/en/us/td/docs/ios/12_0s/feature/guide/lmd_oam.html

3.10. PPPoEoA over ATM AAL5Mux

Reference doc:

http://www.cisco.com/c/en/us/td/docs/ios/bbdsi/configuration/guide/bba_pppoeoa_aal5mux.html

3.11. ATM Conditional Debug Support

Reference doc: <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/atm/configuration/xe-3s/atm-xe-3s-book/atm-con-deb-supp-xe.html>

3.12. PPP over ATM (IETF-Compliant)

Reference doc:

http://www.cisco.com/en/US/docs/ios/bbdsi/configuration/guide/bba_agg_ppp_atm.html

3.13. MQC Policy Map Support on Configured VC Range ATM

Reference doc: <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/atm/configuration/15-s/atm-15-s-book/atm-mqc-vcrange-atm.html>

3.14. Default Route on a PPP Virtual Access Interface

3.15. Modular QoS CLI (MQC) Unconditional Packet Discard

Reference doc: http://www.cisco.com/en/US/docs/ios-xml/ios/qos_plcshp/configuration/15-1mt/qos-plcshp-mod-cli-upd.html

3.16. PPPoE spec conformance with PADT message

Reference doc:

http://www.cisco.com/en/US/docs/ios/12_2t/12_2t2/feature/guide/ftpppoec_support_TSD_Island_of_Content_Chapter.html

3.17. PPPoE enhancement with RFC 4638

Reference doc:

http://www.cisco.com/en/US/docs/ios/12_2t/12_2t2/feature/guide/ftpppoec_support_TSD_Island_of_Content_Chapter.html

3.18. IP to ATM CoS, per-VC WFQ and CBWFQ QoS: PPPoE QoS Markings of .1P bits in S (AOL)

3.19. QoS: PPPoE QoS Markings of .1P bits in S (AOL)

Reference doc: http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_mqc/configuration/xe-3s/asr1000/qos-mqc-xe-3s-asr-1000-book/qos-pppgec.html

3.20. IP-to-ATM CoS

Reference doc:

http://www.cisco.com/c/en/us/td/docs/ios/12_2/qos/configuration/guide/fqos_c/qcfip_atm.html

3.21. LLQ (Low Latency Queueing)

Reference doc: http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_conmgt/configuration/xe-3s/asr1000/qos-conmgt-xe-3s-asr1000-book/qos-conmgt-llq-pps.html

http://www.cisco.com/c/en/us/td/docs/ios/12_0s/feature/guide/fsllq26.htm

3.22. QoS on Dialer

Reference doc: http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_conavd/configuration/15-mt/qos-conavd-15-mt-book/qos-conavd-dial.html

3.23. VC bundling

Reference doc: <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/atm/configuration/xe-3s/asr1000/atm-xe-3s-asr1000-book/atm-cfg-atm-xe.html>

4. Show and Debug commands

Router#show controller vdsl 0/1/0

Controller VDSL 0/1/0 is UP

Daemon Status: UP

XTU-R (DS)	XTU-C (US)
Chip Vendor ID:	'BDCM'
Chip Vendor Specific:	0x0000
Chip Vendor Country:	0xB500
Modem Vendor ID:	'CSCO'
Modem Vendor Specific:	0x4602
Modem Vendor Country:	0xB500
Serial Number Near:	FOC18086ML0
	15.5(201409)

Serial Number Far:

Modem Version Near: 15.5(20140908:060834

Modem Version Far: 0x9186

Modem Status: TC Sync (Showtime!)

DSL Config Mode: AUTO

Trained Mode: G.993.2 (VDSL2) Profile 17a

TC Mode: PTM

Selftest Result: 0x00

DELT configuration: disabled

DELT state: not running

Failed full inits: 0

Short inits: 0

Failed short inits: 0

Modem FW Version: 4.14L.04

Modem PHY Version: A2pv6F039h.d24o_rc1

Line 0:

XTU-R (DS) XTU-C (US)

Trellis: ON OFF

SRA: disabled disabled

SRA count: 0 0

Bit swap: enabled enabled

Bit swap count: 0 0

Line Attenuation: 2.0 dB 0.0 dB

Signal Attenuation: 0.0 dB 0.0 dB

Noise Margin: 31.1 dB 0.0 dB

Attainable Rate: 139871 kbits/s 20001 kbits/s

Actual Power: 13.3 dBm - 6.7 dBm

Per Band Status: D1 D2 D3 U0 U1 U2 U3

Line Attenuation(dB): 2.1 2.3 1.9 N/A 0.0 0.0 N/A

Signal Attenuation(dB): 2.1 2.3 1.8 N/A 0.0 0.0 N/A

Noise Margin(dB): 32.3 30.6 30.5 N/A 0.0 0.0 N/A

Total FECC: 0 0

Total ES: 0 0

Total SES: 0 0

Total LOSS: 0 0

Total UAS: 79 79

Total LPRS: 0 0

Total LOFS: 0 0

Total LOLS: 0 0

DS Channel1 DS Channel0 US Channel1 US Channel0

Speed (kbps): 0 49998 0 20001

SRA Previous Speed: 0 0 0 0

Previous Speed: 0 49998 0 20001

Reed-Solomon EC: 0 0 0 0

CRC Errors: 0 0 0 0

Header Errors:	0	0	0	0
Interleave (ms):	0.00	12.00	0.00	0.00
Actual INP:	0.00	5.01	0.00	0.00

Training Log : Stopped

Training Log Filename : flash:vdslog.bin

Router#show interface atm 0/2/0

ATM0/2/0 is up, line protocol is up
Hardware is NIM-VAB-A, address is 30f7.0d55.402e (bia 30f7.0d55.402e)
MTU 1800 bytes, sub MTU 1800, BW 2679 Kbit/sec, DLY 100 usec,
reliability 255/255, txload 1/255, rxload 1/255
Encapsulation ATM, loopback not set
Keepalive not supported
Encapsulation(s): AAL5
8 maximum active VCs, 0 current VCCs
ATM Dynamic Bandwidth Enabled.
VC Auto Creation Disabled.
VC idle disconnect time: 300 seconds
4 carrier transitions
Last input never, output never, output hang never
Last clearing of "show interface" counters never
Input queue: 0/375/0/0 (size/max/drops/flushes); Total output drops: 0
Queueing strategy: fifo
Output queue: 0/40 (size/max)
5 minute input rate 0 bits/sec, 0 packets/sec
5 minute output rate 0 bits/sec, 0 packets/sec
0 packets input, 128789 bytes, 0 no buffer
Received 0 broadcasts (0 IP multicasts)
0 runts, 0 giants, 0 throttles
0 input errors, 0 CRC, 0 frame, 0 overrun, 0 ignored, 0 abort
0 packets output, 0 bytes, 0 underruns
0 output errors, 0 collisions, 1 interface resets
0 unknown protocol drops
0 output buffer failures, 0 output buffers swapped out

Router#show interface ethernet 0/1/0

Ethernet0/1/0 is up, line protocol is up
Hardware is NIM-VAB-A, address is 30f7.0d55.4026 (bia 30f7.0d55.4026)
MTU 1500 bytes, BW 20001 Kbit/sec, DLY 400 usec,
reliability 255/255, txload 1/255, rxload 1/255
Encapsulation ARPA, loopback not set
Keepalive not supported
Full Duplex, 1000Mbps, media type is Internal
output flow-control is unsupported, input flow-control is unsupported
ARP type: ARPA, ARP Timeout 04:00:00
Last input never, output 00:00:27, output hang never
Last clearing of "show interface" counters never
Input queue: 0/375/0/0 (size/max/drops/flushes); Total output drops: 0
Queueing strategy: fifo

```

Output queue: 0/40 (size/max)
5 minute input rate 0 bits/sec, 0 packets/sec
5 minute output rate 0 bits/sec, 0 packets/sec
  0 packets input, 0 bytes, 0 no buffer
  Received 0 broadcasts (0 IP multicasts)
  0 runts, 0 giants, 0 throttles
  0 input errors, 0 CRC, 0 frame, 0 overrun, 0 ignored
  0 watchdog, 0 multicast, 0 pause input
  21 packets output, 9184 bytes, 0 underruns
  0 output errors, 0 collisions, 1 interface resets
  0 unknown protocol drops
  0 babbles, 0 late collision, 0 deferred
  0 lost carrier, 0 no carrier, 0 pause output
  0 output buffer failures, 0 output buffers swapped out

```

Router#show atm vc

Codes: DN - DOWN, IN - INACTIVE

		VCD /	Peak Av/Min Burst							
Interface	Name	VPI	VCI	Type	Encaps	SC	Kbps	Kbps	Cells	St
0/2/0.1	7	0	199	PVC	SNAP	UBR	2679			UP
				(C)	UBR	0				
0/2/0.2	8	0	200	PVC	SNAP	UBR	2679			UP
				(C)	UBR	0				

4.1 Module specific show commands

- **show platform software subslot <slot>/<subslot> module firmware**
 - Displays firmware version, CFE version, build label of both module (base board)
- **show platform software subslot <slot>/<subslot> module status**
 - Displays cpu utilization, memory utilization, firmware status etc
- **show platform hardware subslot <slot>/<subslot> module device help**
 - Displays device information specific to the module (e.g. Phy, Non-Interface Registers)
- **show platform hardware subslot <slot>/<subslot> module host-if status**
 - Displays config and status for the host interface port(s) (i.e. ports connected to the backplane switch) of baseboard
- **show platform hardware subslot <slot>/<subslot> module host-if statistics**
 - Displays link statistics for the host interface port(s) (i.e. ports connected to the backplane switch)
 -
- **show platform hardware subslot <slot>/<subslot> module interface <interface name> status**
 - Displays status, config & IID for specified user-visible interface

- show platform hardware subslot <slot>/<subslot> module interface <interface name> statistics
 - Displays link statistics including FC info for specified user-visible interface

Router#show platform software subslot 0/1 module firmware

Avg Load info

1.00 0.87 0.46 1/45 603

Kernel distribution info

Linux version 3.4.11-rt19 (gopasaha@blr-atg-001) (gcc version 4.6.2 (Buildroot 2011.11)) #3 SMP PREEMPT Fri Aug 22 14:25:19 IST 2014

Module firmware versions

Modem Fw Version: 4.14L.04

Modem Phy Version: A2pv6F039h.d24o_rc1

Modem Up time

0D 0H 8M 37S

Router#show platform software subslot 0/1 module status

Process and Memory

Mem: 42936K used, 76680K free, 0K shrd, 3156K buff, 9548K cached

CPU: 0% usr 0% sys 0% nic 100% idle 0% io 0% irq 0% sirq

Load average: 1.00 0.87 0.47 1/45 607

PID	PPID	USER	STAT	VSZ	%MEM	CPU	%CPU	COMMAND
538	537	admin	S <	6016	5%	0	0%	dslmgmt
536	1	admin	S <	6016	5%	1	0%	dslmgmt
537	536	admin	S <	6016	5%	0	0%	dslmgmt
515	322	admin	S	4056	3%	1	0%	tr64c -m 0
521	520	admin	S	3932	3%	0	0%	consoled
323	322	admin	S	3832	3%	1	0%	ssk
322	1	admin	S	3600	3%	0	0%	/bin/smd
312	311	admin	S	2976	2%	1	0%	/bin/swmdk
313	311	admin	S	2976	2%	1	0%	/bin/swmdk
311	310	admin	S	2976	2%	0	0%	/bin/swmdk
310	1	admin	S	2976	2%	1	0%	/bin/swmdk
607	606	admin	R <	1680	1%	1	0%	/usr/bin/top -b -n 1 -d 30
1	0	admin	S	1676	1%	1	0%	init
520	1	admin	S	1676	1%	0	0%	-/bin/sh -l -c consoled
606	538	admin	S <	1672	1%	1	0%	sh -c /usr/bin/top -b -n 1 -d 30
362	322	admin	S	1552	1%	1	0%	dhcpd
516	322	admin	S	1480	1%	0	0%	dsldiagd
326	322	admin	S	1432	1%	1	0%	dnsproxy
510	2	admin	SW	0	0%	0	0%	[dsl0]
241	2	admin	SW	0	0%	0	0%	[bcmsw_rx]
145	2	admin	SW	0	0%	0	0%	[mtdblock0]

```

260 2 admin SW 0 0% 1 0% [bcmsw_timer]
12 2 admin SW 0 0% 0 0% [kworker/u:1]
206 2 admin SW 0 0% 0 0% [bcmFlwStatsTask]
5 2 admin SW 0 0% 0 0% [kworker/u:0]
10 2 admin SW 0 0% 0 0% [kworker/0:1]
8 2 admin SW 0 0% 1 0% [kworker/1:0]
50 2 admin SW 0 0% 1 0% [bdi-default]
69 2 admin DW 0 0% 1 0% [skbFreeTask]
9 2 admin SW 0 0% 1 0% [ksoftirqd/1]
88 2 admin SW 0 0% 1 0% [fsnotify_mark]
6 2 admin SW 0 0% 0 0% [migration/0]
7 2 admin SW 0 0% 1 0% [migration/1]
87 2 admin SWN 0 0% 1 0% [kswapd0]
156 2 admin SW< 0 0% 0 0% [linkwatch]
160 2 admin SW< 0 0% 0 0% [deferwq]
11 2 admin SW< 0 0% 1 0% [khelper]
152 2 admin SW 0 0% 1 0% [kworker/1:1]
48 2 admin SW 0 0% 0 0% [sync_supers]
261 2 admin SW 0 0% 0 0% [bcmsw]
52 2 admin SW< 0 0% 1 0% [kblockd]
2 0 admin SW 0 0% 1 0% [kthreadd]
3 2 admin SW 0 0% 0 0% [ksoftirqd/0]
4 2 admin SW 0 0% 0 0% [kworker/0:0]
89 2 admin SW< 0 0% 1 0% [crypto]

```

Processors utilization

Linux 3.4.11-rt19 ((none)) 01/01/70 _mips_ (2 CPU)

	CPU	%usr	%nice	%sys	%iowait	%irq	%soft	%steal	%guest	%idle
00:08:47	all	0.22	0.00	2.51	0.00	0.00	0.16	0.00	0.00	97.10
00:08:47	0	0.25	0.00	3.21	0.00	0.00	0.32	0.00	0.00	96.22
00:08:47	1	0.20	0.00	1.82	0.00	0.00	0.01	0.00	0.00	97.98

Interrupts

	CPU0	CPU1
0:	8373	11905 BCM63xx IPI
7:	517384	524820 BCM63xx timer
9:	12	0 BCM63xx_no_unmask brcm_9
10:	2133	0 BCM63xx_no_unmask brcm_10
13:	0	965 BCM63xx_no_unmask serial
21:	0	0 BCM63xx_no_unmask brcm_21
22:	0	0 BCM63xx_no_unmask brcm_22
31:	7665	0 BCM63xx_no_unmask dsl
34:	0	0 BCM63xx_no_unmask brcm_34
35:	1	0 BCM63xx_no_unmask brcm_35
39:	0	0 BCM63xx_no_unmask brcm_39
89:	0	0 BCM63xx_no_unmask brcm_89
91:	0	0 BCM63xx_no_unmask brcm_91
ERR:	0	

System status

cpu 235 0 2654 102409 0 0 174 0 0 0


```

Mapped:      2768 kB
Shmem:       0 kB
Slab:        26324 kB
SReclaimable: 552 kB
SUnreclaim:   25772 kB
KernelStack:  704 kB
PageTables:   232 kB
NFS_Unstable: 0 kB
Bounce:       0 kB
WritebackTmp: 0 kB
CommitLimit:  59808 kB
Committed_AS: 4896 kB
VmallocTotal: 1032116 kB
VmallocUsed:  1536 kB
VmallocChunk: 1028232 kB

```

Router#show platform hardware subslot 0/1 module interface ethernet 0/1/0 statistics

Mode: PTM IID : 1

Queue Stats	LP	HP
Throttles	0	0
Enables	0	0
Throttles Ref	0	0
Enables Ref	55	55
Throttled	0	0
Tx Packets	14	0
Tx Bytes	6046	0
Tx Q Drops	0	0
Rx Packets	0	NA
Rx Bytes	0	NA
Rx Q Drops	0	NA
Max Q Depth	400	400
Q Depth	0	0
XON Q Depth	25	25
XOFF Q Depth	35	35

End of XDSL Interface Statistics

Router#show platform hardware subslot 0/1 module interface atm 0/1/0 statistics

Mode: ATM IID:3 PVC:8/37

=====

Queue Stats	LP	HP
Throttles	0	0
Enables	0	0
Throttles Ref	0	0
Enables Ref	1543	1543
Throttled	0	0
Tx Packets	7306	0
Tx Bytes	277628	0
Tx Q Drops	0	0

Rx Packets	0	NA
Rx Bytes	0	NA
Rx Q Drops	0	NA
Max Q Depth	400	400
Q Depth	0	0
XON Q Depth	96	96
XOFF Q Depth	100	100

End of XDSL Interface Statistics

Router#show platform hardware subslot 0/1 module device help

```

help      The current information
conn     Conn mgr details
rp       RP details
rgmii    BCM switch port RGMII details
mips     BCM switch port MIPS details
steering  Steering driver details
dma      BCM switch and xtm DMA details

```

Router#show platform hardware subslot 0/1 module device conn

```

Connection Manager Statistics
Total number of packets used by NGIO is: 1 (2 Kbytes)
Processing statistics, processed: 427
Queue depth: current: 0 max: 5
handler (ms): min/avg/max: 0/0/0
NGIO (ms): min/avg/max: 0/0/10
statistics per invocation: avg: 1 max: 6
Corrupted packet Overrun: errors 0
Corrupted packet Underrun errors: 0
packet out of memory errors: 0
          local           remote
          pkts in pkts out errors   pkts in pkts out errors
Control Point: 0: Last update was   280 ms ago
SAP    7:  0   0   0   0   0   0
SAP    6:  0   0   0   0   0   0
SAP    5:  0   0   0   0   0   0
SAP    4:  0   0   0   0   0   0
SAP    3:  0   0   0   0   0   0
SAP    2: 14  85   0  68  13   0
SAP    1: 12 873   0 872  12   0
SAP    0: 402 328   0 326  401   0
Total  : 428 1286   0 1266  426   0
Heartbeats   Local   Remote
State: HB_INACTIVE HB_ACTIVE
      in   184    28
      out   28   184
acks in   28   183
acks out  184    28
lost     0     0
resets   0     0

```

```
Grand Total: 428 1286 0 1266 426 0
```

Router#show platform hardware subslot 0/1 module device rp

Reliable Protocol Statistics

```
link 0    packets in    435
link 0    packets out   1346
link 0    acks in     1342
link 0    acks out    435
link 0    retries      2
link 0    timeouts      0
link 0    delete errors 0
link 0    errors        0
link 0    transmit errors 0
link 0    revision errors 0
link 0    duplicates      0
link 0    out of sequence 0
link 0    out of window    0
link 0    current queue depth 0
link 0    max queue depth 14
link 0    processed      435
link 0    delivered      435
link 0    minimum latency(ms) 0
link 0    maximum latency(ms) 120
link 0    average latency(ms) 3
```

Router#show platform hardware subslot 0/1 module device rgmii

RGMII Tx Stats

```
-----  
1762802 tx_octets_lo, 0 tx_octets_hi  
0 tx_drop_pkts, 273 tx_qos_pkts  
11 tx_bcast_pkts, 272 tx_mcast_pkts  
14152 tx_icast_pkts, 0 tx_col  
0 tx_single_col, 0 tx_multi_col  
0 tx_defer, 0 tx_late_col  
0 tx_excess_col, 0 tx_framein_disc  
0 tx_pause_pkts, 102618 tx_qos_octets_lo  
0 tx_qos_octets_hi
```

RGMII Rx Stats

```
-----  
7103314 rx_octets_lo, 0 rx_octets_hi  
0 rx_undersize_pkts, 0 rx_pause_pkts  
0 rx_oversize_pkts, 0 rx_jabber  
0 rx_align_err, 0 rx_fcs_err  
7103314 rx_good_octets_lo, 0 rx_good_octets_hi  
0 rx_drop_pkts, 14092 rx_icast_pkts  
0 rx_mcast_pkts, 2 rx_bcast_pkts  
0 rx_fragments, 0 rx_excess_frame_disc  
0 rx_symbol_err, 9 rx_qos_pkts  
4055 rx_qos_octets_lo, 0 rx_qos_octets_hi
```

```
Router#show platform hardware subslot 0/1 module device dma
```

```
BCMSW DAM info
```

```
-----  
== dma controller registers ==
```

```
controller config: 00000003
```

```
ch: config:int stat:int mask
```

```
rx:00000001:00000000:00000007
```

```
tx:00000000:00000007:00000000
```

```
== sram contents ==
```

```
ch: bd base: status:current bd content
```

```
rx:078ec000:0000000b:08402000:07b37060
```

```
tx:07ae2000:0000004a:003c6110:05e96002
```

```
== MIPS and MISC registers ==
```

```
CPO cause: 00000000
```

```
CPO status: 10008d01
```

```
XTM Rx DMA info
```

```
-----  
Ch 0, NumRxBds: 776, HeadIdx: 1, TailIdx: 1, AssignedBds: 776
```

```
DMA cfg: 0x00000001, intstat: 0x00000000, intmask: 0x00000007
```

```
Ch 1, NumRxBds: 16, HeadIdx: 1, TailIdx: 1, AssignedBds: 16
```

```
DMA cfg: 0x00000001, intstat: 0x00000000, intmask: 0x00000007
```

```
XTM Tx Bonding DMA info
```

```
-----  
No Bonding Information
```

```
XTM Tx DMA info
```

```
-----  
Ch 0, NumTxBds: 400, HeadIdx: 3, TailIdx: 3, FreeBds: 400
```

```
BD RingOffset: 0x00000003, Word1: 0x01bd60f3
```

```
Ch 1, NumTxBds: 400, HeadIdx: 0, TailIdx: 0, FreeBds: 400
```

```
BD RingOffset: 0x00000000, Word1: 0x00000000
```

```
Router#show platform hardware subslot 0/1 module device mips
```

```
MIPS Tx Stats
```

```
-----  
7112517 tx_octets_lo, 0 tx_octets_hi
```

```
0 tx_drop_pkts, 11 tx_qos_pkts
```

```
2 tx_bcast_pkts, 0 tx_mcast_pkts
```

```
14161 tx_ucast_pkts, 0 tx_col
```

```
0 tx_single_col, 0 tx_multi_col
```

```
0 tx_defer, 0 tx_late_col
```

```
0 tx_excess_col, 0 tx_framein_disc
```

```
0 tx_pause_pkts, 4997 tx_qos_octets_lo
```

```
0 tx_qos_octets_hi
```

```
MIPS Rx Stats
```

```
-----  
1780378 rx_octets_lo, 0 rx_octets_hi  
0 rx_undersize_pkts, 0 rx_pause_pkts  
0 rx_oversize_pkts, 0 rx_jabber  
0 rx_align_err, 0 rx_fcs_err  
1780378 rx_good_octets_lo, 0 rx_good_octets_hi  
0 rx_drop_pkts, 14223 rx_unicast_pkts  
272 rx_mcast_pkts, 12 rx_bcast_pkts  
0 rx_fragments, 0 rx_excess_frame_disc  
0 rx_symbol_err, 273 rx_qos_pkts  
102618 rx_qos_octets_lo, 0 rx_qos_octets_hi
```

```
Router#show platform hardware subslot 0/1 module device steering  
Steering drv Data path stats  
Mode: PTM, IID:1  
25 low_watermark, 35 high_watermark  
0 FcDrops  
----Egress path----  
Tx Priority queue :0  
11 RxPkts, 4711 RxBytes, 11 TxPkts, 4711 TxBytes, 0 RxDroppedPkts, 0 RxDroppedBytes  
0 TxDroppedPkts, 0 TxDroppedBytes  
Tx Priority queue :1  
0 RxPkts, 0 RxBytes, 0 TxPkts, 0 TxBytes, 0 RxDroppedPkts, 0 RxDroppedBytes  
0 TxDroppedPkts, 0 TxDroppedBytes  
----Ingress path----  
0 RxPkts, 0 RxBytes  
0 RxDroppedPkts, 0 RxDroppedBytes  
0 TxPkts, 0 TxBytes  
0 TxDroppedPkts, 0 TxDroppedBytes  
Steering drv Control path stats  
1973 pkt2Linux, 225957 pktBytes2Linux  
0 pktDrops, 0 pktCpDrops
```

```
Router#show platform hardware subslot 0/1 module host-if statistics  
Data path counters  
Mode: PTM     IID : 1 Module Datapath Enabled  
----- Egress path -----  
Enet counters  
14795 RxPkts, 7187018 RxBytes, 0 RxErrs, 0 RxDropped  
Steering counters  
Tx Priority queue :0  
13 RxPkts, 5601 RxBytes, 0 RxDroppedPkts  
13 TxPkts, 5601 TxBytes, 0 TxDroppedPkts  
Tx Priority queue :1  
0 RxPkts, 0 RxBytes, 0 RxDroppedPkts  
0 TxPkts, 0 TxBytes, 0 TxDroppedPkts  
NGIO Flow Control Msgs  
LP XON 51 XOFF 0, HP XON 51 XOFF 0, DroppedFCMs 0  
Low Watermark 25 High Watermark 35
```

```

XTM counters
  5 TxPkts, 2225 TxBytes, 0 TxErrs, 0 TxDropped

----- Ingress path -----
XTM counters
  0 RxPkts, 0 RxBytes, 0 RxErrs, 0 RxDropped
Steering counters
  0 RxPkts, 0 RxBytes, 0 RxDroppedPkts
  0 TxPkts, 0 TxBytes, 0 TxDroppedPkts
Enet counters
  15162 TxPkts, 2119357 TxBytes, 0 TxErrs, 0 TxDropped
Steering drv Control path stats
  2531 pkt2Linux, 289693 pktBytes2Linux
  0 pktDrops, 0 pktCpDrops

```

Router#show platform hardware subslot 0/1 module host-if status

```

Host Module L2 info:
CP_MAC: 30.f7.0d.55.40.ac
FFP_DP_MAC: 30.f7.0d.55.40.a9
FFP_FC_MAC: 30.f7.0d.55.40.a9
Module_MAC: d0.72.dc.93.f5.4b
CP VLAN ID: 2351
FFP DP VLAN ID: 2350
FFP HP1 VLAN ID: 2350
FFP HP2 VLAN ID: 2350
FC VLAN ID: 2350
Max CP MTU : 2048

```

Router#show platformm hardware subslot 0/1 module interface ethernet 0/1/0 status

```

PTM Interface IID:1
Channel Status:ENABLE

```

-----End of XDSL Interface Status-----

Other useful CLIs for debugging issues related to packet flow:

- show platform hardware backplaneswitch-manager rp active ffp statistics
- show platform hardware backplaneswitch-manager rp active subslot <subslot> GEO statistics
- Show platform hardware qfp act infra bqs queue out default interface <interface name>
- show platform hardware qfp active interface if-name <interface name>
- show platform hardware qfp active interface if-name <interface name> statistics

- show platform hardware qfp active statistics drop
- show platform hardware qfp active interface statistics clear

4.2 Useful CLIs for debugging issues related to packet flow specific to ATM PVC

```
Router#show platform software atm F0 pvc
Forwarding Manager ATM PVC Information
Interface          VCD   ID   Ing-ID Eg-ID VC State   AOM ID
ATM0/1/0.1          1    0x1004010 0    0    0x1248    378
```

```
Router#show platform hardware qfp active infrastructure bqs interface-string
ATM0/1/0.1.1.1004010 hierarchy detail
```

Interface: ATM0/1/0.1.1.1004010 QFP: 0.0 if_h: 33 Num Queues/Schedules: 5

Queue specifics:

```
Index 0 (Queue ID:0x448, Name: ATM0/1/0.1.1.1004010)
PARQ Software Control Info:
  (cache) queue id: 0x00000448, wred: 0xe79955d0, qlimit (pkts ): 64
  parent_sid: 0x91, debug_name: ATM0/1/0.1.1.1004010
  sw_flags: 0x08000011, sw_state: 0x00000c01, port_uidb: 65503
  orig_min : 0      , min: 0
  min_qos : 0      , min_dflt: 0
  orig_max : 0      , max: 0
  max_qos : 0      , max_dflt: 0
  share   : 1
  plevel  : 0, priority: 65535
  defer_obj_refcnt: 0
  ifm_h: 36, qos_h: 0x00000000, parent_obj_h: 0x00000024
  ifh 33 queue_type 0(NONE)
  qm_obj: 0x00007f81b81c9fa0
  subdevice_id : 0
Statistics:
  tail drops (bytes): 0      , (packets): 0
  total enqs (bytes): 103686     , (packets): 6098
  queue_depth (pkts ): 0
Schedule specifics:
Index 0 (SID:0x91, Name: ATM0/1/0.1.1.1004010)
PARQ Software Control Info:
  sid: 0x91, parent_sid: 0x90
  evfc_fc_id: 0x5200, fc_sid: 0xffff
  obj_id: 0x24, parent_obj_id: 0x20, debug_name: ATM0/1/0.1.1.1004010
  num_entries (active): 1, num_children (max): 1
  presize_hint: 0
  sw_flags: 0x0842002a, sw_state: 0x00000801
```

```

orig_min :0      , min: 0
min_qos :0      , min_dflt: 1045000
orig_max :0      , max: 1045000
max_qos :0      , max_dflt: 1045000
share :1
plevel: 0, service_fragment: False, port_uidb: 65503
priority: 0, defer_obj_refcnt: 0
ifm_h: 36, qos_h: 0x00000000, parent_obj_h: 0x00000020
ifh 33 queue_type 0(NONE)
qm_obj: 0x00007f81b81caa0f0
subdevice_id :0
REM Schedule Info:
Ctl=0x0 (FC_Enabled) Aggregate State=0x0 (XON XON XON)
HP2, priority level 1. Enforced State=XON (XON)
Bytes Left=2147483647, Paks Left=2147483647
Rvd Flow-On Msgs=0, Rvd Flow-Off Msgs=0
Rvd Refresh Msgs=370, Refresh xon_mismatch=0 xoff_mismatch=0
HP1, priority level 2. Enforced State=XON (XON XON)
Bytes Left=0, Paks Left=0
Rvd Flow-On Msgs=0, Rvd Flow-Off Msgs=0
Rvd Refresh Msgs=0, Refresh xon_mismatch=0 xoff_mismatch=0
LP, normal priority. Enforced State=XON (XON XON XON)
Bytes Left=2147483647, Paks Left=2147483647
Rvd Flow-On Msgs=0, Rvd Flow-Off Msgs=0
Rvd Refresh Msgs=370, Refresh xon_mismatch=0 xoff_mismatch=0

```

Schedule specifics:

Index 1 (SID:0x90, Name: ATM0/1/0 UBR COS)

PARQ Software Control Info:

```

sid: 0x90, parent_sid: 0x7f
evfc_fc_id: 0xffff, fc_sid: 0xffff
obj_id: 0x20, parent_obj_id: 0x1c, debug_name: ATM0/1/0 UBR COS
num_entries (active): 1, num_children (max): 1
presize_hint: 0
sw_flags: 0x08520022, sw_state: 0x000000801
orig_min :0      , min: 0
min_qos :0      , min_dflt: 0
orig_max :0      , max: 0
max_qos :0      , max_dflt: 0
share :1
plevel: 0, service_fragment: False, port_uidb: 65504
priority: 0, defer_obj_refcnt: 0
ifm_h: 32, qos_h: 0x00000000, parent_obj_h: 0x0000001c
ifh 0 queue_type 0(NONE)
qm_obj: 0x00007f81b81caa20
subdevice_id :0

```

Schedule specifics:

Index 2 (SID:0x7f, Name: ATM0/1/0)

PARQ Software Control Info:

```

sid: 0x7f, parent_sid: 0x7c
evfc_fc_id: 0x5100, fc_sid: 0xffff
obj_id: 0x1c, parent_obj_id: 0x17, debug_name: ATM0/1/0
num_entries (active): 2, num_children (max): 2
presize_hint: 0

```

```

sw_flags: 0x0842002a, sw_state: 0x000000801
orig_min : 0      , min: 1097000
min_qos : 0      , min_dflt: 1097000
orig_max : 0      , max: 1097000
max_qos : 0      , max_dflt: 1097000
share   : 1
plevel: 0, service_fragment: False, port_uidb: 65525
priority: 0, defer_obj_refcnt: 0
ifm_h: 28, qos_h: 0x00000000, parent_obj_h: 0x000000017
ifh 11 queue_type 0(NONE)
qm_obj: 0x00007f81b81cb0b0
subdevice_id : 0
REM Schedule Info:
Cntl=0x0 (FC_Enabled) Aggregate State=0x0 (XON XON XON)
HP2, priority level 1. Enforced State=XON (XON)
Bytes Left=0, Paks Left=0
Rvd Flow-On Msgs=0, Rvd Flow-Off Msgs=0
Rvd Refresh Msgs=0, Refresh xon_mismatch=0 xoff_mismatch=0
HP1, priority level 2. Enforced State=XON (XON XON)
Bytes Left=0, Paks Left=0
Rvd Flow-On Msgs=0, Rvd Flow-Off Msgs=0
Rvd Refresh Msgs=0, Refresh xon_mismatch=0 xoff_mismatch=0
LP, normal priority. Enforced State=XON (XON XON XON)
Bytes Left=0, Paks Left=0
Rvd Flow-On Msgs=0, Rvd Flow-Off Msgs=0
Rvd Refresh Msgs=0, Refresh xon_mismatch=0 xoff_mismatch=0
Schedule specifics:
Index 3 (SID:0x7c, Name: Licensed Shaper)
PARQ Software Control Info:
sid: 0x7c, parent_sid: 0x0
evfc_fc_id: 0xffff, fc_sid: 0xffff
obj_id: 0x17, parent_obj_id: 0x0, debug_name: Licensed Shaper
num_entries (active): 5, num_children (max): 5
presize_hint: 2
sw_flags: 0x08022208a, sw_state: 0x00000001
orig_min : 0      , min: 4000000000
min_qos : 0      , min_dflt: 4000000000
orig_max : 0      , max: 4000000000
max_qos : 0      , max_dflt: 4000000000
share   : 1
plevel: 0, service_fragment: False, port_uidb: 0
priority: 0, defer_obj_refcnt: 0
ifm_h: 23, qos_h: 0x00000000, parent_obj_h: 0x000000000
ifh 0 queue_type 0(NONE)
qm_obj: 0x00007f81b81cbf20
subdevice_id : 0

```

- **show platform hardware qfp active interface platform ATM0/1/0.1.1.1004010 path**
- **show platform hardware qfp active interface if-name atm0/1/0.1 statistics**

4.3 DSL debug commands

```
Router#debug vdsl ?
  all      Enable all VDSL debug options
  controller  VDSL controller
  daemon    VDSL daemon debug
  ipc       IPC message exchanges
  mib      debug MIB messages
```

4.4 Collecting training-log

To start training log collection

```
Router#debug vdsl controller 0/1/0 training log
VDSL Controller VDSL 0/1/0 - Training debugging is on
```

To stop training log collection

```
Router#no debug vdsl controller 0/1/0 training log
[VDSL_DIAG_LOG] recv 158991 bytes, written 158991 bytes
[VDSL_DIAG_LOG]: File written sucessfully..
VDSL Controller VDSL 0/1/0 - Training debugging is off
Router#
```

By default training log is collected in the file flash:vdsilog.bin_<slot>-<subslot> .

Example:

```
Router#sh controller vdsl 0/1/0
Controller VDSL 0/1/0 is UP
```

Daemon Status: UP

XTU-R (DS)	XTU-C (US)
Chip Vendor ID: 'BDCM'	'BDCM'
Chip Vendor Specific: 0x0000	0x544D
Chip Vendor Country: 0xB500	0xB500
Modem Vendor ID: 'CSCO'	'BDCM'
Modem Vendor Specific: 0x4602	0x544D
Modem Vendor Country: 0xB500	0xB500
Serial Number Near: FOC18426DR9 4351/K9	15.5(201412
Serial Number Far:	12:161930
Modem Version Near:	15.5(20141202:161930
Modem Version Far:	0x544d

Modem Status: TC Sync (Showtime!)
DSL Config Mode: AUTO
Trained Mode: G.992.5 (ADSL2+) Annex A

TC Mode: ATM

Selftest Result: 0x00
DELT configuration: disabled
DELT state: not running

Failed full inits: 0
Short inits: 0
Failed short inits: 0

Modem FW Version: 4.14L.04
Modem PHY Version: A2pv6F039h.d24o_rc1

Line 0:

	XTU-R (DS)	XTU-C (US)
Trellis:	ON	ON
SRA:	disabled	disabled
SRA count:	0	0
Bit swap:	enabled	enabled
Bit swap count:	669	383
Line Attenuation:	3.5 dB	1.7 dB
Signal Attenuation:	3.1 dB	0.0 dB
Noise Margin:	9.4 dB	5.9 dB
Attainable Rate:	15912 kbytes/s	1379 kbytes/s
Actual Power:	18.0 dBm	12.2 dBm
Total FECC:	176	176
Total ES:	43	0
Total SES:	0	0
Total LOSS:	0	0
Total UAS:	50	50
Total LPRS:	0	0
Total LOFS:	0	0
Total LOLS:	0	0

	DS Channel1	DS Channel0	US Channel1	US Channel0
Speed (kbps):	NA	13073	NA	1045
SRA Previous Speed:	NA	0	NA	0
Previous Speed:	NA	0	NA	0
Total Cells:	NA	1479777783	NA	2179031143
User Cells:	NA	388927	NA	6870
Reed-Solomon EC:	NA	176	NA	176
CRC Errors:	NA	47	NA	0
Header Errors:	NA	335	NA	0
Interleave (ms):	NA	1.99	NA	1.94
Actual INP:	NA	0.15	NA	0.77

Training Log : Stopped

Training Log Filename : **flash:vdsllog_0-1.bin**

User can modify the file in which training logs be stored before starting the training log collection procedure by configuring **training log filename flash:<user-filename>**.

Example:

```
Router#conf t
Enter configuration commands, one per line. End with CNTL/Z.
Router(config)#controller vdsl 0/1/0
Router(config-controller)#training log filename flash:mytraininglog_file
Router(config-controller)#exit

Router#show controller vdsl 0/1/0
Controller VDSL 0/1/0 is UP

Daemon Status:      UP

          XTU-R (DS)      XTU-C (US)
Chip Vendor ID:    'BDCM'        'BDCM'
Chip Vendor Specific: 0x0000      0x544D
Chip Vendor Country: 0xB500      0xB500
Modem Vendor ID:   'CSCO'        'BDCM'
Modem Vendor Specific: 0x4602      0x544D
Modem Vendor Country: 0xB500      0xB500
Serial Number Near: FOC18426DR9 4351/K9 15.5(201412
Serial Number Far:
Modem Version Near: 15.5(20141202:161930
Modem Version Far:  0x544d

Modem Status:      TC Sync (Showtime!)
DSL Config Mode:   AUTO
Trained Mode:      G.992.5 (ADSL2+) Annex A

TC Mode:           ATM
Selftest Result:   0x00
DELT configuration: disabled
DELT state:        not running

Failed full inits: 0
Short inits:       0
Failed short inits: 0

Modem FW Version:  4.14L.04
Modem PHY Version: A2pv6F039h.d24o_rc1
```

Line 0:

	XTU-R (DS)	XTU-C (US)
Trellis:	ON	ON
SRA:	disabled	disabled
SRA count:	0	0
Bit swap:	enabled	enabled
Bit swap count:	669	383
Line Attenuation:	3.5 dB	1.7 dB
Signal Attenuation:	3.1 dB	0.0 dB
Noise Margin:	8.8 dB	5.9 dB

Attainable Rate:	15464 kbytes/s	1379 kbytes/s
Actual Power:	18.0 dBm	12.2 dBm
Total FECC:	176	176
Total ES:	43	0
Total SES:	0	0
Total LOSS:	0	0
Total UAS:	50	50
Total LPRS:	0	0
Total LOFS:	0	0
Total LOLS:	0	0

	DS Channel1	DS Channel0	US Channel1	US Channel0
Speed (kbps):	NA	13073	NA	1045
SRA Previous Speed:	NA	0	NA	0
Previous Speed:	NA	0	NA	0
Total Cells:	NA	1484200375	NA	2179384795
User Cells:	NA	388991	NA	6938
Reed-Solomon EC:	NA	176	NA	176
CRC Errors:	NA	47	NA	0
Header Errors:	NA	335	NA	0
Interleave (ms):	NA	1.99	NA	1.94
Actual INP:	NA	0.15	NA	0.77

Training Log : Stopped

Training Log Filename : **flash:mytraininglog_file**

5. Sample configurations

5.1 Sample MLPPP configs and show commands

```
!
interface Ethernet0/3/0
no ip address
load-interval 30
no negotiation auto
pppoe enable
pppoe-client dial-pool-number 2
!
!
interface Dialer2
bandwidth 55000
ip address negotiated
encapsulation ppp
load-interval 30
dialer pool 1
dialer-group 1
ppp authentication chap
```

```

ppp chap hostname cisco
ppp multilink
ppp multilink endpoint string mlpp
!
Router#show pppoe session
  1 client sessions
  Uniq ID PPPoE RemMAC      Port          VT VA State
  N/A   268 a44c.119d.d671 Et0/3/0    Di2 Vi2 UP
                c067.af94.c2a8           UP
Router#

```

```

Router#show ppp multilink active
Virtual-Access3
  Bundle name: cisco1/mlpp/cisco/mlpp
  Remote Username: cisco1
  Remote Endpoint Discriminator: [1] mlpp
  Local Username: cisco
  Local Endpoint Discriminator: [1] mlpp
  Bundle up for 05:40:46, total bandwidth 89000, load 196/255
  Receive buffer limit 24384 bytes, frag timeout 1000 ms
  Bundle is Distributed
  Dialer interface is Dialer1
    0/0 fragments/bytes in reassembly list
    0 lost fragments, 0 reordered
    0/0 discarded fragments/bytes, 0 lost received
    0xD received sequence, 0xC2AE3 sent sequence
  Platform Specific Multilink PPP info
    NOTE: internal keyword not applicable on this platform
    Interleaving: Disabled, Fragmentation: Disabled
    Member links: 2 (max 16, min not set)
      Vi1, since 05:40:46, 206250 weight, 1496 frag size
      Vi2, since 05:40:41, 127500 weight, 1496 frag size

```

```

Router#show platform hardware qfp active feature mlp client bundle Virtual-Access3
  Bundle Interface: Virtual-Access3
  Bundle State: Up
  Platform Interface Handle: 35
  QFP Interface Handle: 26
  QFP Interface uIDB Handle: Rx 65510, Tx 65510
  Shadow Base: 0x020E19D0, Size: 1160
  Num Links: 2, Next Link: 2, Enabled Links Mask: 0x0003
  Tx Channel: 0x32, Tx Queue ID: 0x451, Tx Flow Control SID: 0x9f
  Max Frags: 0x0, Lost Fragment Timeout: 1000
  Max Frag Size: 65535, Frag Delay: 30
  RX Class Buffer Size: 24384
  MRRU: 1524, Peer MRRU: 1524
  Bundle Bandwidth: 89000 kbps
  RX Classes: 1, TX Classes: 1
  Bundle Flags: 0x00000011, RX DP Flags: 0x04, TX DP Flags: 0x20
  Outstanding datapath proxy requests:
    Bundle Create: 0, Update: 0, Remove: 0

```

```

Links Add: 0, Delete: 0
Member Link Interfaces:
Interface: EVSI20
    Platform Interface Handle: 20
    QFP Interface Handle: 17
    QFP Interface uIDB Handle: Rx 65519, Tx 65519
    Shadow Base: 0x02075CA0, Size: 218
    TX Chan: 52, P1 Queue ID: 1107, P2 Queue ID: 0
    Link Bandwidth: 55000 kbps, Link Weight: 206250, Link Qlimit: 2286
    Link Optimal Frag Size: 1496, Max Frag Size: 65535
    Rewrite Len w/ PID: 2 Rewrite Len w/o PID: 0
    Rewrite String: 00, 3d
    Outstanding datapath proxy requests:
        Links Add: 0, Update: 0, Delete: 0
Interface: EVSI21
    Platform Interface Handle: 21
    QFP Interface Handle: 18
    QFP Interface uIDB Handle: Rx 65518, Tx 65518
    Shadow Base: 0x01D48550, Size: 218
    TX Chan: 51, P1 Queue ID: 1109, P2 Queue ID: 0
    Link Bandwidth: 34000 kbps, Link Weight: 127500, Link Qlimit: 2286
    Link Optimal Frag Size: 1496, Max Frag Size: 65535
    Rewrite Len w/ PID: 2 Rewrite Len w/o PID: 0
    Rewrite String: 00, 3d
    Outstanding datapath proxy requests:
        Links Add: 0, Update: 0, Delete: 0

```

```

Router#show platform hardware qfp active feature mlp datapath bundle Virtual-
Access3 detail
QFP: 0.0 - Bundle Rx Interface: Virtual-Access3, State: UP
Rx Bundle uIDB: 65510
    Num Links: 2, Num Classes: 1, MRRU: 1524
    Defined Links: 0x0003, Enabled Links: 0x0003
    Config Flags: 0x04 (EVSI, MCMP: Disabled, Strict Seq Check: Enabled)
    Buffer Limit: 24384 bytes per class, Lost Frag Timeout: 1000 ms
    Stats Non-MLP Encapped Rx: 0 packets
        Meta Packet Drop: 0, Attn Sync Drop: 0
        No Buffer: 0, Invalid Class: 0
        Hit Buffer Limit: 0, Rx Pkt Exceeds MRRU: 0
        Lost Frag Timeout: 0
    Reassembly QID: 0x000003F8, Qlimit: 2000, Qdepth: 0
    Bundle SB: 0x33445150, SB Size: 144
Rx Classes:
Class: 0
    Expected Seq Number: 0x00000D, In Order/In Sync Links: 0x0003/0x0003
    Stats Rx Buffered: 0/0 fragments/bytes
        Rx Fragmented: 0 fragments
        Rx Unfragmented: 13 packets
        Rx Post Reassembly: 13 packets
        Rx Discarded: 0/0 fragments/bytes

```

```

        Rx NULL Frags:      0, Rx Lost:      0
        Rx Out of Order:   0, Rx Rcv'd Lost:  0
        Reorder/Reassembly Stats:
            Reassembly Packet:    0/0 fragments/bytes
            Staged Packets:     0 (S1-empty,S2-empty)
            Inflight Packets:   0
        Class SB: 0x3334D910, SB Size: 272
        Rx Member Links:
            Member Link Interface: EVSI20, State: UP
                Rx Link uIDB: 65519, Link ID: 0, Link Mask: 0x0001
                    Config Flags: 0x01 (EVSI)
                    Class Link Buffered Fragments
                        0          0
                    Link SB: 0x33470430, SB Size: 32
            Member Link Interface: EVSI21, State: UP
                Rx Link uIDB: 65518, Link ID: 1, Link Mask: 0x0002
                    Config Flags: 0x01 (EVSI)
                    Class Link Buffered Fragments
                        0          0
                    Link SB: 0x33470410, SB Size: 32
        QFP: 0.0 - Bundle Tx Interface: Virtual-Access3, State: UP
            Tx Bundle uIDB: 65510
                Num Links: 2, Num Classes: 1, Peer MRRU: 1524
                Member Links Defined: 0x0003 Enabled: 0x0003 Congested(HP/LP): 0x0000/0x0000
                Bundle Equal Cost Frag Size: 1496
                Config Flags: 0x20 (EVSI, MCMP: Disabled, MCMP Encap Seq: No,
                    Interleave: Disabled, Fragmentation: Disabled
                    NCP MLP Encaped: Yes, NCP Tx Link ID: 0)
                EVSI First Member Link Encap Type: 1, EVSI L2 Overhead: 20
                Bundle Flow Control SID: 0x9F, SID Update In Prog: No, Bundle Flags: 0x01
                    Flow Control Timer: Stopped, Xoff Timer Tics: 0, Check Interval: 4572
                    MLP FC: Xon, SW FC: Full-Xon, HW FC: Full-Xon
                    HW FC Full Xoff Events: 6410, HW FC LP Xoff Events: 0
                    Bundle Load Cycle ID (HP/LP): 0/2594, Next Tx Link ID (HP/LP): 0/1
            Link Link Queue Cycle ID Cycle Tx Bytes Queue Depth
                ID Weight Limit HP/LP HP/LP HP(agg)/LP
                0 206250 9 0/2594 0/98444 0/0
                1 127500 9 0/2594 0/98314 0/0
                Stats Non-MLP Encapped Tx:      2 packets
                Non-MLP Priority Interleaved:  0 packets
                Tx Drop:      0, Tx ESS Packet Drop:  0
                Invalid Class: 0
            Bundle SB: 0x34F6C800, SB Size: 256
        Tx Classes:
            Class: 0
                Next Send Seq Number: 0x976A97
                Stats Tx Pre Frag Packets: 127363735 packets
                    Tx Fragmented:      0 fragments
                    Tx Unfragmented:   127363735 packets
                    Tx Frag Interleaved: 0 fragments
                    Tx Unfrag Interleaved: 0 packets
            Class SB: 0x3334DD20, SB Size: 64
        Tx Member Links:

```

```

Member Link Interface: EVSI20, Parent: Ethernet0/1/0, State: UP
  Tx Link uIDB: 65519, Link ID: 0, Link Mask: 0x0001
  Config Flags: 0x01 (EVSI)
  EVSI Parent Encap Type: 1, EVSI L2 Overhead: 20
  Link Weight: 206250, Frag Size: 1496
  P1 Tx QID: 0x00000453, Qdepth: 0
  P2 Tx QID: 0x00000000, Qdepth: 0
  Default Tx QID: 0x00000452, Qdepth: 0
  L2 Rewrite String: 003D
    Rewrite length w/ PID: 2, Length w/o PID: 0
    Link SB: 0x34FAB0C0, SB Size: 144
Member Link Interface: EVSI21, Parent: Ethernet0/3/0, State: UP
  Tx Link uIDB: 65518, Link ID: 1, Link Mask: 0x0002
  Config Flags: 0x01 (EVSI)
  EVSI Parent Encap Type: 1, EVSI L2 Overhead: 20
  Link Weight: 127500, Frag Size: 1496
  P1 Tx QID: 0x00000455, Qdepth: 0
  P2 Tx QID: 0x00000000, Qdepth: 0
  Default Tx QID: 0x00000454, Qdepth: 0
  L2 Rewrite String: 003D
    Rewrite length w/ PID: 2, Length w/o PID: 0
    Link SB: 0x34FAB030, SB Size: 144

```

5.2. Sample PPPoA configuration

```

interface ATM0/2/0.1 point-to-point
  ip unnumbered Loopback0
  no atm enable-ilmi-trap
  pvc 71/200
  oam-pvc 0
  encapsulation aal5mux ppp dialer
  dialer pool-member 151
!
interface Dialer151
  ip address negotiated
  encapsulation ppp
  load-interval 30
  dialer pool 151
  ppp chap hostname BBIP45687587@adslmax.bt.com
  ppp chap password 0 cisco1
!
dialer-list 1 protocol ip permit
!
```

5.3. Sample PPPoEoA configuration

```

interface ATM0/1/0
no ip address
no atm enable-ilmi-trap
!
interface ATM0/1/0.10 point-to-point
no atm enable-ilmi-trap
cdp enable
pvc 22/62
ubr 1045
encapsulation aal5mux pppoe-client
pppoe-client dial-pool-number 120
!
!
interface Dialer120
mtu 1492
ip address negotiated
ip nat outside
encapsulation ppp
load-interval 30
dialer pool 120
dialer-group 1
ppp mtu adaptive
ppp chap hostname test@cisco.com
ppp chap password 0 cisco
ppp ipcp address required
ppp link reorders
!
```

6 Known limitations/Restrictions

6.1 PVC under sub-interface only

In IOS-XE, ATM PVCs can be configured under ATM sub-interfaces only. PVC configuration is not allowed under the main ATM interface.

6.2 Maximum of 8 PVCs supported on a physical interface

Under a single physical interface, maximum of 8 PVCs can be configured. Under each sub-interface maximum of one PVC can be configured. Hence would be able to configure 8 sub-interfaces, with one PVC configured under each sub-interface.

6.3 MLPPP bundle across DSL interfaces

When MLPPP bundle is made across DSL interfaces, interleave delay of the lines should be same.

- Bundling of line 0 and line 1 in case of PTM bond
- Bundling of 2 or more dsl physical interfaces

Example: In the below PTM bond case, interleave delay for line 0 in upstream is 5ms whereas for line 1 it is 8ms. Due to this difference, mlPPP bundle between line 0 and line 1 would not work as the mlPPP buffer overflow would occur. The same would be applicable in downstream direction as well if the interleave delay is different.

```
Router#sh controller vdsl 0/3/0
Controller VDSL 0/3/0 is UP
```

```
Daemon Status:      RUNNING
```

	XTU-R (DS)	XTU-C (US)
Chip Vendor ID:	'BDCM'	'BDCM'
Chip Vendor Specific:	0x0000	0xA450
Chip Vendor Country:	0xB500	0xB500
Modem Vendor ID:	'CSCO'	'BDCM'
Modem Vendor Specific:	0x4602	0x0000
Modem Vendor Country:	0xB500	0xB500
Serial Number Near:	FOC18086MJP	15.5(201405
Serial Number Far:		03:010710
Modem Version Near:	15.5(20140503:010710	
Modem Version Far:	0xa450	

Modem Status(L0):	TC Sync (Showtime!)
Modem Status(L1):	TC Sync (Showtime!)
DSL Config Mode:	AUTO
Trained Mode(L0):	G.993.2 (VDSL2) Profile 17a
Trained Mode(L1):	G.993.2 (VDSL2) Profile 17a

TC Mode:	PTM Bonded
Selftest Result:	0x00
DELT configuration:	disabled
DELT state:	not running
Failed full inits:	0
Short inits:	0
Failed short inits:	0

Modem FW Version:	4.14L.02
Modem PHY Version:	A2pvbF039h.d24j12

Vendor Version: ^@*L^X^P

Line 0:

	XTU-R (DS)			XTU-C (US)			
Trellis:	ON			OFF			
SRA:	disabled			disabled			
Bit swap:	enabled			enabled			
Profile 30a:	disabled						
Bit swap count:	0			0			
Line Attenuation:	1.3 dB			0.0 dB			
Signal Attenuation:	0.0 dB			0.0 dB			
Noise Margin:	0.0 dB			0.0 dB			
Attainable Rate:	0 kbits/s			0 kbits/s			
Actual Power:	0.0 dBm			13.0 dBm			
Per Band Status:	D1	D2	D3	U0	U1	U2	U3
Line Attenuation(dB):	1.2	1.2	1.5	N/A	0.0	0.0	N/A
Signal Attenuation(dB):	1.2	1.2	1.5	N/A	0.0	0.0	N/A
Noise Margin(dB):	0.0	0.0	0.0	N/A	0.0	0.0	N/A
Total FECC:	0			0			
Total ES:	0			0			
Total SES:	0			0			
Total LOSS:	0			0			
Total UAS:	234			234			
Total LPRS:	0			0			
Total LOFS:	0			0			
Total LOLS:	0			0			

	DS Channel1	DS Channel0	US Channel1	US Channel0
Speed (kbps):	0	80032	0	54844
SRA Previous Speed:	0	80032	0	53873
Previous Speed:	0	0	0	0
Reed-Solomon EC:	0	0	0	0
CRC Errors:	0	0	0	0
Header Errors:	0	0	0	0
Interleave (ms):	0.00	3.00	0.00	5.00
Actual INP:	0.00	1.00	0.00	0.10

Line 1:

	XTU-R (DS)			XTU-C (US)			
Trellis:	ON			OFF			
SRA:	disabled			disabled			
Bit swap:	enabled			enabled			
Profile 30a:	disabled						

Bit swap count:	0	0					
Line Attenuation:	0.0 dB	0.0 dB					
Signal Attenuation:	0.0 dB	0.0 dB					
Noise Margin:	0.0 dB	0.0 dB					
Attainable Rate:	0 kbits/s	0 kbits/s					
Actual Power:	0.0 dBm	0.0 dBm					
Per Band Status:	D1 Line Attenuation(dB): Signal Attenuation(dB): Noise Margin(dB):	D2 0.0 0.0 0.0	D3 0.0 0.0 0.0	U0 0.0 0.0 0.0	U1 0.0 0.0 0.0	U2 0.0 0.0 0.0	U3 0.0 0.0 0.0
Total FECC:	0	0					
Total ES:	0	0					
Total SES:	0	0					
Total LOSS:	0	0					
Total UAS:	0	0					
Total LPRS:	0	0					
Total LOFS:	0	0					
Total LOLS:	0	0					

	DS Channel1	DS Channel0	US Channel1	US Channel0
Speed (kbps):	0	80032	0	53873
SRA Previous Speed:	0	80032	0	53873
Previous Speed:	0	0	0	0
Reed-Solomon EC:	0	0	0	0
CRC Errors:	0	0	0	0
Header Errors:	0	0	0	0
: 0.00 3.00 0.00 8.00				
Actual INP:	0.00	1.00	0.00	0.10

Training Log : Stopped

Training Log Filename : flash:vdsilog.bin

Router#

6.4 ATM Virtual Circuit Bundles license requirement

As compared to T-train products, APP License is required to support this feature on this module in IOS-XE.

6.5 ATM Multilink PPP Support on Multiple VCs and MLPPP bundling of interfaces.

Below are the recommended configurations for the feature to work seamlessly.

1. It is recommended to have dynamic bandwidth enabled under ATM interface.
2. It is recommended not to configure “bandwidth x” under dialer interfaces. If configured, ensure that the configured bandwidth is always above dsl line rate.