

Addendum Release Notes for Cisco Wireless LAN Controllers and Lightweight Access Points for Special Build 8.10.181.3

Base Code: 8.10.181.0
Special Build: 8.10.181.3

8.10 MR8 Escalation Release

Image Name	MD5 Checksum	Comments
AS_7500_8_10_181_3.aes	efff9975d7d2c8ed264fcfe61431789d	5520, 8540 WLC Image
AS_3500_8_10_181_3.aes	1b65264a394b7fbcb0d9fdf748a14766	3504 WLC Image
AS_CTVM_SMALL_8_10_181_3.aes	167e445542942ada68b5af167909765c	vWLC Image for Small Scale Deployment
AS_CTVM_LARGE_8_10_181_3.aes	97d397355b1cb1644281afd98b225b4f	vWLC Image for Large Scale Deployment
ap1g5-ME-k9w8-tar.202210262130	e880e1f336cc14e93e6fece34da86f28	1815 Mobility Express Image
ap1g4-ME-k9w8-tar.202210262141	aefbe0e145a247b31d7a76584f5dc82e	1850 Mobility Express Image
ap3g3-ME-k9w8-tar.202210262135	94bdc8a23328cb10375883e8df30d4c7	2800, 3800, 4800 Mobility Express Image
ap_bundle_8.10.181.3	39f6ede3c9fd0c6eb0c8e449d0a0a487	Mobility Express Bundle Image
AP_BUNDLE_7500_8_10_181_3.aes	0c9942cd28bf7151115936e0706d5d8a	AP Bundle for 9117 AP Platform
AP_BUNDLE_3500_8_10_181_3.aes	b4e6b2a6f7fdb4d5f2b0ddfe168b567	AP Bundle for 9117 AP Platform
AP_BUNDLE_CTVM_SMALL_8_10_181_3.aes	90126d1391e293fe3c5dee30457c3468	AP Bundle for 9117 AP Platform
AP_BUNDLE_CTVM_LARGE_8_10_181_3.aes	fbfd795250f541d6b06ed1fa72589497	AP Bundle for 9117 AP Platform

Escalation image is a temporary release delivery of fix until next CCO release is available. **Customers are requested to migrate to next CCO release when fixes are made available.** We request you to drop a note to “wnbu-escalation@cisco.com” with TAC Case #, Escalation image version, Bug affected where escalation image is used and what scale the deployment happen (AP, WLC, Client count). Any feedback would be appreciated either via TAC or this alias.

8.10.181.3 is an Escalation build published from the 8.10.181.0 CCO image and it is an engineering special that resolves the following additional caveat(s):

8.10.181.3

CSCwd37092 Slow TCP downloads, failing TLS authentications in 8.10.181.0/17.3.6 - 2800/3800/4800 series
CSCwc78435 9130 sending incorrect channel list on out of band DFS event causing client connectivity issues

ENGINEERING SPECIAL USE DISCLAIMER

The Engineering Special fix supplied herewith is a Temporary Software Module which has undergone limited testing. This temporary software module is provided “AS-IS” without warranty under the terms of the END USER LICENCE FOR THIS PRODUCT. Please use this software at your own risk. The intention for this code fix is for you to use in your production environment until a released version is available.

Americas Headquarters

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved. 95134-1706 USA

This code is supported by the TAC organization. Please report all comments, suggestions, and problems about this code directly to wnbu-escalation@cisco.com. If you are satisfied with the solution, please inform the alias.

Contact wnbu-escalation@cisco.com with any questions.



Americas Headquarters

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved. 95134-1706 USA