=~=~~=~=~=~=~=~=~= PuTTY log 2020.01.10 17:33:02 =~=~=~=~=~=~=~=~=~=~=~= AP00f2.8b81.3bbc> Not in Bound state. *Mar 1 00:05:01.012: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Not in Bound state. *Mar 1 00:05:28.064: %LWAPP-4-CLIENTEVENTLOG: Invoking capwap discovery *Mar 1 00:05:31.520: %DHCP-6-ADDRESS_ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc AP00f2.8b81.3bbc>en Password: Password: AP00f2.8b81.3bbc#sh ip int br IP-Address OK? Method Status Interface Protocol BVI1 10.18.90.105 YES DHCP up up GigabitEthernet0 unassigned NO unset up up AP00f2.8b81.3bbc# Not in Bound state. *Mar 1 00:06:48.035: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Not in Bound state. *Mar 1 00:07:37.083: %CAPWAP-3-DHCP RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:07:40.539: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) Not in Bound state. *Mar 1 00:08:39.590: %CAPWAP-3-DHCP_RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:08:43.046: %DHCP-6-ADDRESS_ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc

AP00f2.8b81.3bbc# Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61)e (209.18.47.62) AP00f2.8b81.3bbc#erase startup-config % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#erase startup-config % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#conf t % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#conf terase startup-config % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#en AP00f2.8b81.3bbc#config % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#conf t % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#conf tigen Not in Bound state.rase startup-config % Invalid input detected at '^' marker. AP00f2.8b81.3bbc# *Mar 1 00:09:42.098: %CAPWAP-3-DHCP RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. AP00f2.8b81.3bbc# *Mar 1 00:09:45.554: %DHCP-6-ADDRESS_ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc erase startup-config AP00f2.8b81.3bbc#erase startup-configconf t erase startup-config % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#

Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) AP00f2.8b81.3bbc#erase startup-configderase startup-configoerase startup-config erase startup-config % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#do wr e % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#do wr eerase startup-config Not in Bound state.erase startup-config conf t iq *Mar 1 00:10:44.605: %CAPWAP-3-DHCP_RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP.en rase startup-configconf t erase startupconfigconf t erase startup-confign config terase startup-configdo erase startup-configwr e AP00f2.8b81.3bbc# *Mar 1 00:10:48.061: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc AP00f2.8b81.3bbc#shd i ip int br Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61)OK? Method Status Interface IP-Address Protocol 10.18.90.105 BVT1 YES DHCP up gu GigabitEthernet0 unassigned NO unset up gu AP00f2.8b81.3bbc# (209.18.47.62) AP00f2.8b81.3bbc# Not in Bound state. *Mar 1 00:11:47.112: %CAPWAP-3-DHCP RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:11:50.568: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) Not in Bound state. *Mar 1 00:12:49.620: %CAPWAP-3-DHCP_RENEW: Could not discover WLC.

Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:12:53.076: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) Not in Bound state. *Mar 1 00:13:52.127: %CAPWAP-3-DHCP RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:13:55.583: %DHCP-6-ADDRESS_ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) 1 00:14:52.479: %LINEPROTO-5-UPDOWN: Line protocol on Interface *Mar GigabitEthernet0, changed state to up Not in Bound state. *Mar 1 00:14:55.134: %CAPWAP-3-DHCP_RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:14:57.674: %LINK-6-UPDOWN: Interface BVI1, changed state to au *Mar 1 00:14:58.674: %LINEPROTO-5-UPDOWN: Line protocol on Interface BVI1, changed state to up *Mar 1 00:15:03.590: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61)AP00f2.8b81.3bbc# (209.18.47.62)sh ip int br Interface IP-Address OK? Method Status Protocol 10.18.90.105 BVI1 YES DHCP up uр NO unset up GigabitEthernet0 unassigned up AP00f2.8b81.3bbc#sh ip int br Interface IP-Address **OK?** Method Status Protocol BVI1 10.18.90.105 YES DHCP up up GigabitEthernet0 unassigned NO unset up up

AP00f2.8b81.3bbc#sh ip int brdo wr e % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#wr e % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#en AP00f2.8b81.3bbc#wr e % Invalid input detected at '^' marker. AP00f2.8b81.3bbc#wr een wr edo wr esh ip int br OK? Method Status Interface IP-Address Protocol BVI1 10.18.90.105 YES DHCP up up GigabitEthernet0 unassigned NO unset up up AP00f2.8b81.3bbc#reload Not in Bound state. Proceed with reload? [confirm] *Mar 1 00:15:57.638: %CAPWAP-3-DHCP_RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. Writing out the event log to flash:/event.log ... Write of event.log done *Mar 1 00:15:59.526: %SYS-5-RELOAD: Reload requested by console. Reload Reason: Reload Command. *Mar 1 00:15:59.530: %LWAPP-5-CHANGED: CAPWAP changed state to DOWN Boot from flash IOS Bootloader - Starting system. FLASH CHIP: Spansion S25FL256 Xmodem file system is available. flashfs[0]: 12 files, 2 directories flashfs[0]: 0 orphaned files, 0 orphaned directories

flashfs[0]: Total bytes: 31936000 flashfs[0]: Bytes used: 6987264 flashfs[0]: Bytes available: 24948736 flashfs[0]: flashfs fsck took 9 seconds. Reading cookie from SEEPROM Base Ethernet MAC address: 00:f2:8b:81:3b:bc File "flash:/ap1g2-rcvk9w8-mx/ap1g2-rcvk9w8-mx" uncompressed and installed, entry point: 0x2004000 executing... Secondary Bootloader - Starting system. FLASH CHIP: Spansion S25FL256 Xmodem file system is available. flashfs[0]: 12 files, 2 directories flashfs[0]: 0 orphaned files, 0 orphaned directories flashfs[0]: Total bytes: 31936000 flashfs[0]: Bytes used: 6987264 flashfs[0]: Bytes available: 24948736 flashfs[0]: flashfs fsck took 9 seconds. Reading cookie from SEEPROM Base Ethernet MAC address: 00:f2:8b:81:3b:bc Secondary bootloader Ethernet not enabled, skip ether_init Boot CMD: 'boot flash:/ap1g2-rcvk9w8-mx/ap1g2-rcvk9w8-xx;flash:/

ap1g2-rcvk9w8-mx/ap1g2-rcvk9w8-xx'

File "flash:/ap1g2-rcvk9w8-mx/ap1g2-rcvk9w8-xx" uncompressed and installed, entry point: 0x100000

executing...

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software – Restricted Rights clause at FAR sec. 52.227–19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227–7013.

> cisco Systems, Inc. 170 West Tasman Drive San Jose, California 95134–1706

Cisco IOS Software, C1600 Software (AP1G2-RCVK9W8-M), Version 15.3(3)JC, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 1986-2015 by Cisco Systems, Inc. Compiled Fri 11-Dec-15 10:43 by prod_rel_team

Initializing flashfs... FLASH CHIP: Spansion S25FL256

flashfs[2]: 12 files, 2 directories flashfs[2]: 0 orphaned files, 0 orphaned directories flashfs[2]: Total bytes: 31808000 flashfs[2]: Bytes used: 6987264 flashfs[2]: Bytes available: 24820736 flashfs[2]: flashfs fsck took 10 seconds. flashfs[2]: Initialization complete. flashfs[3]: 0 files, 1 directories flashfs[3]: 0 orphaned files, 0 orphaned directories flashfs[3]: 0 orphaned files, 0 orphaned directories flashfs[3]: Total bytes: 11999232 flashfs[3]: Bytes used: 1024 flashfs[3]: Bytes available: 11998208 flashfs[3]: flashfs fsck took 0 seconds. flashfs[3]: Initialization complete....done Initializing flashfs. This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately. A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stgrg.html If you require further assistance please contact us by sending email to export@cisco.com. cisco AIR-CAP1602I-A-K9 (PowerPC) processor (revision B0) with 187386K/74672K bytes of memory. Processor board ID FCW2008N910 PowerPC CPU at 533Mhz, revision number 0x2151 Last reset from power-on LWAPP image version 8.2.100.0 1 Gigabit Ethernet interface 32K bytes of flash-simulated non-volatile configuration memory. Base ethernet MAC Address: 00:F2:8B:81:3B:BC Part Number : 73-14671-04 PCB Serial Number : F0C200816GN Top Assembly Part Number : 800-102028-03 Top Assembly Serial Number : FCW2008N910 Top Revision Number : A0 Product/Model Number : AIR-CAP1602I-A-K9 % Please define a domain-name first. ipv6 enable % Invalid input detected at '^' marker. ipv6 address autoconfig % Invalid input detected at '^' marker. ipv6 address dhcp % Invalid input detected at '^' marker. Press RETURN to get started!

*Mar 1 00:00:12.783: APAVC: Initial WLAN Buffers Given to System is 500 1 00:00:12.799: APAVC: WlanPAKs 9355 RadioPaks 8747 *Mar *Mar 1 00:00:13.443: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg config failed, trying backup... *Mar 1 00:00:13.443: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp ap.cfg.bak config failed... *Mar 1 00:00:14.839: %LWAPP-4-CLIENTEVENTLOG: PnP waiting for capwap init *Mar 1 00:00:14.839: %LINK-6-UPDOWN: Interface GigabitEthernet0, changed state to up *Mar 1 00:00:15.663: %SYS-5-RESTART: System restarted --Cisco IOS Software, C1600 Software (AP1G2-RCVK9W8-M), Version 15.3(3)JC, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 1986-2015 by Cisco Systems, Inc. Compiled Fri 11-Dec-15 10:43 by prod_rel_team *Mar 1 00:00:15.663: %SNMP-5-COLDSTART: SNMP agent on host ap is undergoing a cold start *Mar 1 00:00:15.707: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg config failed, trying backup... *Mar 1 00:00:15.711: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg.bak config failed... *Mar 1 00:00:15.711: spamInitRadCfg: recovery image default mode 0 *Mar 1 00:00:15.939: %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0, changed state to up *Mar 1 00:00:16.759: %LINEPROTO-5-UPDOWN: Line protocol on Interface BVI1, changed state to up 1 00:00:18.187: %SSH-5-ENABLED: SSH 2.0 has been *Mar enabledlwapp_crypto_init: MIC Present and Parsed Successfully *Mar 1 00:00:27.687: %LINK-6-UPDOWN: Interface BVI1, changed state to down *Mar 1 00:00:28.687: %LINEPROTO-5-UPDOWN: Line protocol on Interface BVI1, changed state to down%Default route without gateway, if not a point-to-point interface, may impact performance *Mar 1 00:00:34.491: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg config failed, trying backup... *Mar 1 00:00:34.495: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp ap.cfg.bak config failed... *Mar 1 00:00:34.495: %CAPWAP-3-EVENTLOG: No Config Present. PNP required *Mar 1 00:00:34.567: Cert ISSUER (39): cn=Cisco Manufacturing CA SHA2,o=Cisco

*Mar 1 00:00:36.583: %LINK-6-UPDOWN: Interface BVI1, changed state to up *Mar 1 00:00:37.583: %LINEPROTO-5-UPDOWN: Line protocol on Interface BVI1, changed state to up *Mar 1 00:00:40.039: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc AP00f2.8b81.3bbc> %Error opening flash:/capwap-saved-config (No such file or directory) %Error opening flash:/capwap-saved-config-bak (No such file or directory) Not in Bound state. AP00f2.8b81.3bbc> *Mar 1 00:00:53.559: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc e AP00f2.8b81.3bbc>en Password: AP00f2.8b81.3bbc#sh ip int br Interface IP-Address **OK?** Method Status Protocol 10.18.90.105 BVI1 YES DHCP up up GigabitEthernet0 unassigned NO unset up up AP00f2.8b81.3bbc# Not in Bound state. *Mar 1 00:01:14.023: %LWAPP-4-CLIENTEVENTLOG: Invoking capwap discoverv *Mar 1 00:01:17.479: %DHCP-6-ADDRESS_ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc flashfs[0]: 12 files, 2 directories flashfs[0]: 0 orphaned files, 0 orphaned directories flashfs[0]: Total bytes: 31936000 flashfs[0]: Bytes used: 6987264 flashfs[0]: Bytes available: 24948736 flashfs[0]: flashfs fsck took 9 seconds. Reading cookie from SEEPROM Base Ethernet MAC address: 00:f2:8b:81:3b:bc

Secondary Bootloader - Starting system.

FLASH CHIP: Spansion S25FL256

Xmodem file system is available.

flashfs[0]: 12 files, 2 directories

flashfs[0]: 0 orphaned files, 0 orphaned directories

flashfs[0]: Total bytes: 31936000

flashfs[0]: Bytes used: 6987264

flashfs[0]: Bytes available: 24948736

flashfs[0]: flashfs fsck took 9 seconds.

Reading cookie from SEEPROM

Base Ethernet MAC address: 00:f2:8b:81:3b:bc

Secondary bootloader Ethernet not enabled, skip ether_init

Boot CMD: 'boot flash:/ap1g2-rcvk9w8-mx/ap1g2-rcvk9w8-xx;flash:/ ap1g2-rcvk9w8-mx/ap1g2-rcvk9w8-xx'

File "flash:/ap1g2-rcvk9w8-mx/ap1g2-rcvk9w8-xx" uncompressed and installed, entry point: 0x100000

executing...

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software – Restricted Rights clause at FAR sec. 52.227–19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227–7013.

> cisco Systems, Inc. 170 West Tasman Drive San Jose, California 95134–1706

Cisco IOS Software, C1600 Software (AP1G2-RCVK9W8-M), Version 15.3(3)JC, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 1986-2015 by Cisco Systems, Inc. Compiled Fri 11-Dec-15 10:43 by prod_rel_team

Initializing flashfs...
FLASH CHIP: Spansion S25FL256

flashfs[2]: 12 files, 2 directories flashfs[2]: 0 orphaned files, 0 orphaned directories flashfs[2]: Total bytes: 31808000 flashfs[2]: Bytes used: 6987264 flashfs[2]: Bytes available: 24820736 flashfs[2]: flashfs fsck took 10 seconds. flashfs[2]: flashfs fsck took 10 seconds. flashfs[3]: 0 files, 1 directories flashfs[3]: 0 orphaned files, 0 orphaned directories flashfs[3]: 0 orphaned files, 0 orphaned directories flashfs[3]: Total bytes: 11999232 flashfs[3]: Bytes used: 1024 flashfs[3]: Bytes available: 11998208 flashfs[3]: flashfs fsck took 0 seconds. flashfs[3]: Initialization complete....done Initializing flashfs.

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:

http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com. cisco AIR-CAP1602I-A-K9 (PowerPC) processor (revision B0) with 187386K/74672K bytes of memory. Processor board ID FCW2008N91Q PowerPC CPU at 533Mhz, revision number 0x2151 Last reset from power-on LWAPP image version 8.2.100.0 1 Gigabit Ethernet interface 32K bytes of flash-simulated non-volatile configuration memory. Base ethernet MAC Address: 00:F2:8B:81:3B:BC Part Number : 73-14671-04 PCB Serial Number : F0C200816GN Top Assembly Part Number : 800-102028-03 Top Assembly Serial Number : FCW2008N91Q Top Revision Number : A0 : AIR-CAP1602I-A-K9 Product/Model Number % Please define a domain-name first. ipv6 enable % Invalid input detected at '^' marker. ipv6 address autoconfig % Invalid input detected at '^' marker. ipv6 address dhcp % Invalid input detected at '^' marker. Press RETURN to get started! *Mar 1 00:00:12.783: APAVC: Initial WLAN Buffers Given to System is 500 *Mar 1 00:00:12.799: APAVC: WlanPAKs 9355 RadioPaks 8747 *Mar 1 00:00:13.443: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg config failed, trying backup... *Mar 1 00:00:13.447: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg.bak config failed... 1 00:00:14.843: %LWAPP-4-CLIENTEVENTLOG: PnP waiting for capwap *Mar init

*Mar 1 00:00:14.843: %LINK-6-UPDOWN: Interface GigabitEthernet0, changed state to up *Mar 1 00:00:15.667: %SYS-5-RESTART: System restarted --Cisco IOS Software, C1600 Software (AP1G2-RCVK9W8-M), Version 15.3(3)JC. RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 1986-2015 by Cisco Systems, Inc. Compiled Fri 11-Dec-15 10:43 by prod rel team *Mar 1 00:00:15.667: %SNMP-5-COLDSTART: SNMP agent on host ap is undergoing a cold start *Mar 1 00:00:15.711: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg config failed, trying backup... *Mar 1 00:00:15.711: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg.bak config failed... *Mar 1 00:00:15.711: spamInitRadCfg: recovery image default mode 0 *Mar 1 00:00:15.939: %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0, changed state to up *Mar 1 00:00:16.759: %LINEPROTO-5-UPDOWN: Line protocol on Interface BVI1, changed state to up 1 00:00:18.191: %SSH-5-ENABLED: SSH 2.0 has been *Mar enabledlwapp_crypto_init: MIC Present and Parsed Successfully 1 00:00:27.687: %LINK-6-UPDOWN: Interface BVI1, changed state to *Mar down *Mar 1 00:00:28.687: %LINEPROTO-5-UPDOWN: Line protocol on Interface BVI1, changed state to down%Default route without gateway, if not a point-to-point interface, may impact performance *Mar 1 00:00:34.491: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg config failed, trying backup... *Mar 1 00:00:34.495: %LWAPP-3-CLIENTERRORLOG: Load nvram:/ lwapp_ap.cfg.bak config failed... *Mar 1 00:00:34.495: %CAPWAP-3-EVENTLOG: No Config Present. PNP required *Mar 1 00:00:34.567: Cert ISSUER (39): cn=Cisco Manufacturing CA SHA2,o=Cisco *Mar 1 00:00:36.583: %LINK-6-UPDOWN: Interface BVI1, changed state to up *Mar 1 00:00:37.583: %LINEPROTO-5-UPDOWN: Line protocol on Interface BVI1, changed state to up *Mar 1 00:00:40.039: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc AP00f2.8b81.3bbc>e %Error opening flash:/capwap-saved-config (No such file or directory) %Error opening flash:/capwap-saved-config-bak (No such file or directorv)n AP00f2.8b81.3bbc>

Not in Bound state.en Password: AP00f2.8b81.3bbc# *Mar 1 00:00:53.559: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc AP00f2.8b81.3bbc#sh ip int br Interface IP-Address **OK?** Method Status Protocol BVT1 10.18.90.105 YES DHCP up up GigabitEthernet0 unassigned NO unset up up AP00f2.8b81.3bbc# Not in Bound state. *Mar 1 00:01:14.023: %LWAPP-4-CLIENTEVENTLOG: Invoking capwap discovery *Mar 1 00:01:17.479: %DHCP-6-ADDRESS_ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc *Mar 1 00:02:38.442: %CDP_PD-4-POWER_OK: All radios disabled -NON_CISCO-NO_CDP_RECEIVED inline power source Not in Bound state. *Mar 1 00:02:53.986: %DHCP-6-ADDRESS_ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Not in Bound state. *Mar 1 00:03:43.037: %CAPWAP-3-DHCP_RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:03:46.493: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) Not in Bound state. *Mar 1 00:04:45.541: %CAPWAP-3-DHCP RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:04:48.997: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62)

Not in Bound state. *Mar 1 00:05:48.044: %CAPWAP-3-DHCP RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:05:51.500: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) Not in Bound state. *Mar 1 00:06:50.547: %CAPWAP-3-DHCP_RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:06:54.003: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) Not in Bound state. *Mar 1 00:07:53.055: %CAPWAP-3-DHCP_RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:07:56.511: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) Not in Bound state. *Mar 1 00:08:55.558: %CAPWAP-3-DHCP RENEW: Could not discover WLC. Either IP address is not assigned or assigned IP is wrong. Renewing DHCP IP. *Mar 1 00:08:59.014: %DHCP-6-ADDRESS ASSIGN: Interface BVI1 assigned DHCP address 10.18.90.105, mask 255.255.255.0, hostname AP00f2.8b81.3bbc Translating "CISCO-CAPWAP-CONTROLLER.dscsrouter.com"...domain server (209.18.47.61) (209.18.47.62) AP00f2.8b81.3bbc#sh ip int br Interface IP-Address OK? Method Status Protocol 10.18.90.105 YES DHCP BVI1 up up

unassigned NO unset up

GigabitEthernet0 up AP00f2.8b81.3bbc#