





We are trying to get to this end state design.
We've stopped short of it due to ACI Warning Message referencing other border leaf ports that may be affected.

ACI Deployment

Spine 101
Spine 102
Border Leaf 201
Border Leaf 202



N9K-C9396PX



N9K-C9396PX

- Notes:**
- 1. All vPC connections depicted are 40Gb
 - 2. Spine connections are 100Gb