Tools & Resources Software Advisor

IOME	Start	Hardware/Soft	ware =	eature/Softw		ompare Fe	atures	Research S	oftware			
UPPORT	Start	rial uw al e/Son	ware	eature/Soltw		ompare re	atures	tesearch o	ontware	_		
OOLS & RESOURCES												
Software Advisor					Yo	ur Selectio	ns			\sim		
		Select the train that optimizes your preferred										
		balance of Stability, Functionality, and Minimum Requirements (Help I)				tegory	Routers					
	rtoquironi	(<u>100</u> L)	, ,		Ту	pe ries	N/A					
		- Field Nationa / Security Articarias					7600 Serie					
	-	 Field Notices / Security Advisories 				odel	7606-S Ro					
					05			System Sof				
					En	gine/CPU	7600-RSP	720/MSFC4				
					Fe	ature Set/L	icense Sele	ection (<u>edit</u>)		X		
					Feature ADVANCED IP SERVICES SSH set/License							
	Compatib	lo Polossos	(a orted by	train)						\sim		
	Compatib	le Releases - ((SUILED DY		lity		Minimum	Doguirom	onto	Download		
	Train7	Stability Life Cycle	Bugs	Functiona Software	-			Requirem	Hardware	Software Image	Minimum	A
	Train/		(severity 1 & 2)					Flash ⁶	bootROM 3	(Latest Maintenance Release in Train) 4	Compatible Release ⁵	r c
	15.2S	<u>Early</u> Deployment	<u>View</u>	<u>View</u>		<u>View</u>	1024	256	N/A	15.2(4)S <u>c7600rsp72043-</u> advipservicesk9- <u>mz.15.2-4.S</u>	15.2(1)S1	I
	15.1S	<u>Maintenance</u> Deployment	<u>View</u>	<u>View</u>		<u>View</u>	1024	256	N/A	15.1(3)S4 <u>c7600rsp72043-</u> advipservicesk9- <u>mz.15.1-3.S4</u>	15.1(1)S1	
	15.0S	<u>Maintenance</u> Deployment	<u>View</u>	<u>View</u>		<u>View</u>	1024	256	N/A	15.0(1)S6 <u>rsp72043-</u> advipservicesk9- <u>mz.15.0-1.S6</u> <u>c7600rsp72043-</u> advipservicesk9- <u>mz.15.0-1.S6</u>	15.0(1)S1	
	12.2SRE	<u>Maintenance</u> Deployment	<u>View</u>	<u>View</u>		<u>View</u>	1024	256	N/A	12.2(33)SRE6 <u>c7600rsp72043-</u> <u>advipservicesk9-</u> <u>mz.12.2-</u> <u>33.SRE6</u>	12.2(33)SRE0a	ı
	12.2SRD	<u>Early</u> Deployment	<u>View</u>	<u>View</u>		<u>View</u>	1024	256	N/A	12.2(33)SRD8 <u>c7600rsp72043-</u> advipservicesk9- <u>mz.12.2-</u> 22.5RD9	12.2(33)SRD	
	12.2SRC	<u>Early</u> Deployment	<u>View</u>	<u>View</u>		<u>View</u>	1024	256	N/A	33.SRD8 12.2(33)SRC6 <u>c7600rsp72043-</u> <u>advipservicesk9-</u> <u>mz.12.2-</u> 33.SRC6	12.2(33)SRC	
	12.2SRB	<u>Early</u> Deployment	<u>View</u>	<u>View</u>		<u>View</u>	1024	128	N/A	33.SRC6 12.2(33)SRB7 <u>c7600rsp72043-</u> <u>advipservicesk9-</u> <u>mz.12.2-</u> 33.SRB7	12.2(33)SRB	

¹ Minimum DRAM is only a minimum. Actual DRAM required may vary, especially with larger routing tables.

2 Some hardware is only supported in certain feature sets/Licenses. When so, the total minimum DRAM will be the sum of the minimum DRAM required by the software image and that required by your selected hardware.

3 Unlike with hardware bootROM, the software bootflash version (where applicable) should match that of your installed Cisco IOS system softwar image.

⁴ It is a recommended best practice to backup your software configuration file before upgrading.

⁵ Minimum compatible release is the lowest maintenance release that supports your selections and was available for download at the time of da entry. The possibility exists that a lower maintenance release in the same train supports your selections but is no longer available for you to dowr ⁶FLÁG IMAGE : A Éxplanation: This image requires more memory than currently (as per show version) installed on your device. If you select this image, please upgrade your memory before upgrading to it. 7FLAG IMAGE : • Explanation: Current Train of router as reported by "show version".

Back

Small Business Service Provider Home

Industries

Contacts

Contact Cisco Find a Partner Blogs New sletters Field Notices Security Advisories Documentation

Communities

Collaboration Developer Network Learning Network Support (NetPro) Corporate Social Responsibility Environmental Sustainability Human Netw ork Career Opportunities

Offers

Special Offers Financing Options

Contacts | # Feedback | Help | Site Map | Terms & Conditions | Privacy Statement | Cookie Policy | Trademarks