

Addendum Release Notes for Cisco Wireless LAN Controllers and Lightweight Access Points for Special Build 7.3.103.10

Base Code: 7.3.101.0
Special Build: 7.3.103.10

Engineering Special Build

7.3.103.10 is a build from the 7.3.101.0 and it is an engineering special that resolves the following additional caveat(s):

- [CSCua58554 AAA override dynamic RADIUS VLAN HREAP Flexconnect broken in 7.2](#)
- [CSCub77220 WLC crashed in task 'emWeb' during flexconnect ACL delete operation](#)
- [CSCuc47106 Mobility fails when there is an error in sending bcst traffic](#)
- [CSCtx03556 TACACS user login failure on 5508 WLC running 7.0.116.0](#)
- [CSCuc13536 Local AP mode does not work in AIR-CAP1552E-K-K9](#)
- [CSCub27807 WLC sending incorrect NMSP Measurement notification for Rogue APs](#)
- [CSCuc34199 Silent crash on WLC running 7.3.101.0](#)
- [CSCub65575 WLC forwarding wired-to-wired bcst ARP to centrally switched clients](#)
- [CSCuc56697 8500 with 6K AP and 64K client coredump](#)
- [CSCty12524 BRA from MAG is missing Service Selection having APN & HOA options](#)
- [CSCuc24324 The WiSM2 crashed multiple times when acting as MAG at PMIPv6 task.](#)
- [CSCub67462 ethernet bridged \(Vlan Tagging\) broken in 7.3](#)
- [CSCuc16850 radio stops transmitting - transmit queues are full](#)
- [CSCuc62460 AP http profiler crash on multiple codenomicon tests](#)
- [CSCud07497 7500/8500 sends wrong pmk cache timer for 11r client to mobility peers](#)
- [CSCuc15636 Crash on webauth redirect processing](#)
- [CSCud08022 HA breaks for WLC8510 when the WLC under scale \(6k APs, 64k Clients\)](#)
- [CSCuc90975 Users able to move between ISE SSIDs without authenticating to the SSID](#)
- [CSCuc37505 WLAN config not saved after reboot with Radius NAC enabled](#)
- [CSCto2968 New Memory leak sshpm, on sshencode. line 252](#)
- [CSCub88183 WLC Crashing at emWeb instruction: ewaFormSubmit_login_callback](#)
- [CSCud00484 HA - Clients Stay in 8021X_REQD After Switchback From Second to Primary](#)
- [CSCud22588 Cleanup : mmListen:Failed to release a mutual exclusion object](#)

CSCud97713 Add ap-ethernet-mac and ap-ethernetmac-ssid to CallStationIdType for TWC

CSCuc69522 CWA anchor WLAN sends no TCP SYN ACK to client with IPV4Multicast GW MAC

CSCuc03576 ARP problems with MAPs

CSCud33577 Flexconnect APs stuck in limbo when DHCP server is unreachable

CSCuc84338 Fenway AP showing up in Local mode instead of MAP or RAP mode

ENGINEERING SPECIAL USE DISCLAIMER

The Engineering Special fix supplied herewith is a Temporary Software Module which has undergone limited testing. This temporary software module is provided “AS-IS” without warranty under the terms of the END USER LICENCE FOR THIS PRODUCT. Please use this software at your own risk. The intention for this code fix is for you to use in your production environment until a released version is available.

This code is supported by the TAC organization. Please report all comments, suggestions, and problems about this code directly to wmbu_escalation_external@cisco.com. If you are satisfied with the solution, please inform the alias.

Contact wmbu_escalation_external@cisco.com with any questions.



Americas Headquarters

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved. 95134-1706 USA